

CRC CHEMICALS U.S.A./CRC INDUSTRIES, INC. -- HEAVY DUTY DEGREASER (AEROSOL) #3095 --
6850-01-244-9614

===== Product Identification =====

Product ID:HEAVY DUTY DEGREASER (AEROSOL) #3095

MSDS Date:01/01/1987

FSC:6850

NIIN:01-244-9614

MSDS Number: BGRGL

=== Responsible Party ===

Company Name:CRC CHEMICALS U.S.A./CRC INDUSTRIES, INC.

Address:885 LOUIS DRIVE

City:WARMINSTER

State:PA

ZIP:18974-2820

Country:US

Info Phone Num:215-674-4300

Emergency Phone Num:215-674-4

300/800-424-9300(CHEMTREC)

CAGE:10136

=== Contractor Identification ===

Company Name:CRC INDUSTRIES, INC.

Address:885 LOUIS DRIVE

Box:City:WARMINSTER

State:PA

ZIP:18974-2820

Country:US

Phone:215-674-4300/800-424-9300

CAGE:10136

===== Composition/Information on Ingredients =====

Ingred Name:METHYL CHLOROFORM (1,1,1-TRICHLOROETHANE) (SARA III)

CAS:71-55-6

RTECS #:KJ2975000

Fraction by Wt: 72%

OSHA PEL:350 PPM/450 STEL

ACGIH TLV:350 PPM/450STEL;9192

EPA Rpt Qty:1000 LBS

DOT Rpt

Qty:1000 LBS
Ozone Depleting Chemical:1

Ingred Name:PERCHLOROETHYLENE (TETRACHLOROETHYLENE) (SARA III)
CAS:127-18-4
RTECS #:KX3850000
Fraction by Wt: 24%
OSHA PEL:100 PPM
ACGIH TLV:25PPM/100,A3 STEL;94
EPA Rpt Qty:100 LBS
DOT Rpt Qty:100 LBS

Ingred Name:CARBON DIOXIDE
CAS:124-38-9
RTECS #:FF6400000
Fraction by Wt: 4%
OSHA PEL:5000 PPM
ACGIH TLV:5000PPM/30000STEL;93

===== Hazards Identification =====

Effects of
Overexposure:EYE:PAIN,IRR;SKIN:IRR;INH:HEAD
,DIZZ,ANESTH,UNCONSC.

===== First Aid Measures =====

First Aid:INHAL:RMV TO FRESH AIR. IF NOT BRTHNG GIVE CPR; IF BRTHNG
DIFF GIVE OXYGEN. EYE:IMMED FLUSH W/PLENTY OF WATER. SKIN:WASH
W/SOAP & WATER. RMV CONTAM CLTHG & SHOES. INGEST:DO NOT INDUCE
VOMIT. NOTHG BY MOUTH IF UNCONSC. GET MEDICAL ATTN.

===== Fire Fighting Measures =====

Flash Point:N/R,AEROSOL
Lower Limits:7.5
Upper Limits:14.5
Extinguishing Medi
a:WATER FOG
Fire Fighting Procedures:NONE SPECIFIED
Unusual Fire/Explosion Hazard:AEROSOLS MAY EXPLODE IF THEIR
TEMP.EXCEEDS 130F

===== Accidental Release Measures =====

Spill Release Procedures:AREA SHOULD BE VENTILATED AND ABSORBENT USED
TO PICK UP EXCESS MATERIAL.

===== Handling and Storage =====

Handling and Storage Precautions:AVOID PROLONGED SKIN CONTACT OR
BREATHING OF VAPORS-KEEP AEROSOLS AWAY FROM HEAT.
Other

Precautions:SINCE VAPORS ARE HEAVIER THAN AIR,AEROSOLS SHOULD NOT BE USED IN CONFINED AREAS OR LOW SPOTS W/O ADEQUATE VENTILATION.IF VAP.ARE SUSPECTED IN A LOW AREA,DO NOT ENTER W/O SCBA & AN OBSERVER.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:ABOVE TLV USE SELF CONTAINED AIR MASK OR VAPOR MASK.
Ventilation:PROVIDE MECHAN(GEN/LOCAL EXHAUST)VENT TO MAINTN