FILTRON CO.INC FA1480B 5915-00-087-6469 ===================================
Product ID:FA1480B
MSDS Date:01/01/1985
FSC:5915
NIIN:00-087-6469
MSDS Number: BCYJP
=== Responsible Party ===
Company Name:FILTRON CO.INC
Address:148 SWEET HOLLOW RD
City:OLD BETHPAGE
State:NY ZIP:11804-1315
Country:US
Emergency Phone Num:914-699-2000
CAGE:JO764
=== Contractor Identification ===
Company Name:FILTRON CO INC
Address:148 SWEET HOLLOW RD
Box:City:OLD BETHPAGE
State:N
Υ
ZIP:11804-1315
Country:US
Phone:914-699-2000
CAGE:81831
Company Name:FILTRON CO.INC
Address:148 SWEET HOLLOW RD
Box:City:OLD BETHPAGE State:NY
ZIP:11804-1315
Country:US
CAGE:JO764
0/102.007.04
======= Composition/Information on Ingredients ========
Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)
CAS:1336-36-3
RTECS #:TQ1350000
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB
======================================

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTE

CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.
======== Accidental Release Measures =========
Spill Release Procedures:USE ABSORBEN T & DIKES TO PREVENT RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.
=========== Handling and Storage ============
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN C ONTACT Supplemental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR
========= Stability and Reactivity Data =========
STRONG OXIDIZERS
======== Disposal Considerations ===========
Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPE

STINE.CAUSES

## RATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.