

EXXON COMPANY, USA -- ISOPAR M -- 9160-00-322-9367

===== Product Identification =====

Product ID:ISOPAR M

MSDS Date:01/01/1985

FSC:9160

NIIN:00-322-9367

MSDS Number: BDWTB

=== Responsible Party ===

Company Name:EXXON COMPANY, USA

Emergency Phone Num:(713) 656-3424

CAGE:DO850

=== Contractor Identification ===

Company Name:EXXON COMPANY U.S.A.

Box:2180

City:HOUSTON

State:TX

ZIP:77252-2180

Country:US

Phone:713-656-5949 / 713-656-3424

CAGE:29700

Company Name:EXXON COMPANY, USA, A DIV OF EXXON CORP.

Address:800 BELL ST

Box:2180

City:HOUSTON

State:TX

ZIP:77252-2180

Country:US

Phone:713-656-5949 FAX: 713-656-3631

CAGE:DO850

===== Composition/Information on Ingredients =====

Ingred Name:ISOPARAFFINIC PETROLEUM SOLVENTS

Fraction by Wt: 100%

ACGIH TLV:MFG 300 PPM

===== Hazards Identification =====

Effects of Overexposure:INHAL OF HIGH VPR CO

NCS ATTAINABLE AT ELEV
TEMP-DIZZ,HEADACHE,RESP.IRRIT.SKIN-DEFAT,IRRIT,DERMATITIS

===== First Aid Measures =====

First Aid:INHAL: REMOVE TO FRESH AIR. CALL MD. INGEST: DO NOT INDUCE
VOMITING. SKIN: REMOVE CNTMNTD CLOTHING, WASH SKIN W/SOAP & WARM
WATER. EYES: FLUSH W/WATER FOR 15 MIN OR UNTIL IRRITATION SUBSIDES.

===== Fire Fighting Measures =====

Flash Point:77C PMCC

Lower Limits:0.6

Upper Limits:6.5

Extingui

shing Media:FOAM, DRY CHEM, CO*2, WATER FOG OR SPRAY.

Fire Fighting Procedures:ENCL AREA- AIR-SUPP.RESP. AVOID BRTHNG VAPOR
OR FUMES.

Unusual Fire/Explosion Hazard:COMBUSTIBLE-DONT MIX OR STORE W/STRONG
OXIDANTS(CL OR CONC.O*2).DURING FIRE-COOL CONTNRS W/H*2O SPRY

===== Accidental Release Measures =====

Spill Release Procedures:REMOVE IGNITN SOURCES.KEEP PEOPLE AWAY.RECOVER
FREE LIQ.ADD ABSORBENT TO SPILL AREA.AVOID BREATHNG
VAPORS.VENTLATE-OPEN WIND
OWS&DOORS.KEEP PET.PRODCTS OUT OF
SEWERS&WATERCOURSES BY DIKING OR IMPOUNDIN G.ADVISE
AUTHORITIES-PROD.HAS/MAY ENTERWATERWAYS.

===== Handling and Storage =====

Handling and Storage Precautions:KEEP CONTAINERS CLOSED WHEN NOT IN
USE. DO NOT HANDLE OR STORE NEAR HEAT,SPARKS,FLAME OR STRNG
OXIDANTS. USE ONLY W/ADEQUATE VENTLN(=OUTDOORS).

Other Precautions:AVOID BREATHNG VAPORS.AVOID PROLNKD/REPEATED W/SKIN.
REMOVE CNTMNTD CLTHNG, LAUNDER BFRE
REUSE. REMOVE CONTMNTD
SHOES,DRY BFRE REUSE. WASH SKIN THOROUGHLY W/SOAP & WATER AFTER
CONTACT.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:ENCL.SPACES-HYDROCRBN VAPOR CANISTER OR SUPP AIR
RESP PROTECTION.

Ventilation:LOCAL FACE VEL.>69 FPM.MECH-USE EXPLOSION PROOF EQUIP.

Protective Gloves:CHEM RESISTANT

Eye Protection:SPLASH GOGGLE/FACE SHIELD

Other Protective Equipment:CHEM.RESISTANT APRON,OTHER CLTHNG-ABOID
RPTD/PROLNG CNT.

Sup

plemental Safety and Health
BOILING PT IS 207 TO 254C. VAPOR PRESS AT 25C IS