View NSN Online: https://aerobasegroup.es/nsn/3439-00-528-9063

Product ID:308 AC-DC 0.125

MSDS Date:07/24/1986

FSC:3439

NIIN:00-528-9063

MSDS Number: BFCZF === Responsible Party ===

Company Name: ALLOY RODS CORPORATION

Address: WILSON AVENUE

Box:517

City:HANOVER

State:PA ZIP:17331

Info Phone Num:717-637-8911

Emergency Phone Num:717-637-8911

CAGE:84021 === Contractor Identification ===

Company Name: ESAB GROUP INC Address: 801 WILSON AVENUE

Box:517

City:HANOVER

State:PA ZIP:17331 Country:US

Phone:717-637-8911 OR 800-933-7070

CAGE:84021

======= Composition/Information on Ingredients ========

Ingred Name:IRON CAS:7439-89-6

RTECS #:NO4565500

Other REC Limits:5MG/M*3

OSHA PEL:10MG/M*3 ACGIH TLV:5MG/M*3

Ingred Name: NICKEL (SARA III)

CAS:7440-02-0

RTECS #:QR5950000

Other REC Limits:1MG/M*3

OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3; 9192

Ingred Name:CALCI

UM FLUORIDE CAS:7789-75-5

RTECS #:EW1760000

Other REC Limits:2.5MG/M*3

OSHA PEL:2.5 MG/M3 (F)

ACGIH TLV:2.5 MG/M3 (F); 8990

Ingred Name: SODIUM SILICATE

CAS:6834-92-0

RTECS #:VV9275000

Other REC Limits:10MG/M*3(NUISANCE D)

OSHA PEL:10MG/M*3(RESP DUST) ACGIH TLV:0.1MG/M*3(RESP DUST)

Ingred Name:BENTONITE (AS NUISANCE DUST OR PARTICULATES NOT OTHERWISE

REGULATED) CAS:1302-78-9

DTEOD # 0T045

RTECS #:CT9450000

OSHA PEL:15 MG/M3 TOTAL DUST ACGIH TLV:10 MG/M3 TDUST;8990

Ingred Name: CHROMIUM (SARA III)

CAS:74 40-47-3

RTECS #:GB4200000

Other REC Limits: 0.5MG/M*3

OSHA PEL:1 MG/M3

ACGIH TLV:0.5 MG/M3; 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: MANGANESE (SARA III)

CAS:7439-96-5

RTECS #: OO9275000

Other REC Limits:5MG/M*3 (C) OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name: CALCIUM CARBONATE (MARBLE) (LIMESTONE)

CAS:1317-65-3

RTECS #:EV9580000

Other REC Limits:10MG/M*3 OSHA PEL:15 MG/M3 TDUST

ACGIH TLV:10 MG/M3 TDUST; 9192

Ingred Name: SILICA, CRYSTALLINE - QUARTZ

CAS:14808-60-

7 RTECS #: VV7330000 Other REC Limits:0.1MG/M*3(RESP DUST) **OSHA PEL:SEE TABLE Z3** ACGIH TLV:0.1 MG/M3 RDUST;9293 Ingred Name: POTASSIUM SILICATE CAS:1312-76-1 OSHA PEL:10MG/M*3(RESP DUST) ACGIH TLV:0.1MG/M*3(RESP DUST) ========== Hazards Identification ================ Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Health Hazards Acute and Chronic:ACUTE:METALLIC TASTE, NAUSEA, TIGHTNESS OF CHEST, FEVER, DIZZINESS ,DRYNESS,IRRITATION OF EYES,NOSE & THROAT. CHRONIC: EXCESSIVE LEVELS MAY CAUSE BRONCHIAL ASTHMA, LUNG FIBROSIS, SIDEROSIS. ARC RAYS CAN INJUR E EYES & BURN SKIN. ELECTRIC SHOCK CAN KILL. Explanation of Carcinogenicity: CHROMIUM VI IS A HUMAN CARCINOGEN. CHROMIUM III IS A SUSPECTED HUMAN CARCINOGEN. NI IS A SUSPECTED HUMAN CARCINOGEN. Effects of Overexposure:SEE HEALTH HAZARDS. Medical Cond Aggravated by Exposure: AGGRAVATION OF EXISTING RESPIRATORY OR ALLERGIC CONDITIONS. HIGH ER LEVEL OF LUNG RELATED PROBLEMS AMONG SMOKERS. First Aid:REMOVE FROM EXPOSURE & OBTAIN PROMPT MEDICAL ATTENTION. IF UNCONSCIOUS, GIVE OXYGEN. IF NOT BREATHING, GIVE CPR. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS. =========== Fire Fighting Measures ========================== Flash Point:NONE

Extinguishing Media: USE MEDIA APPROPRIATE FOR SURROUNDING FIRE.

Unusual Fire/Explosion Hazard:WE

COMBUSTIBLE PRODUCTS.
========== Accidental Release Measures ==========
Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE & PLACE IN APPROPRIATE DISPOSAL CONTAINER.
=========== Handling and Storage ============
Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES. MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES. AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA.
======================================
Respiratory Protection:FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR IN CONFINED SPACES OR WHERE VENTILATION DOES NOT KEEP EXPOSURE BELOW TLV.
Ventilation:LOCAL EXHAUST TO MAINTAIN BELOW TLV.
Protective Gloves:WELDER'S GLOVES. Eye Protection:HELMET OR FACE SHIELD WITH FILTER LENS.
Other Protective Equipment:SUBSTANTIAL DARK CLOTH,ARM
PROTECTOR,APRON,HAT,SHOULDER PROTECTION. Work Hygienic Practices:WASH HANDS THOROUGHLY BEFORE EAT
ING,SMOKING,USING SANITARY FACILITIES.
Supplemental Safety and Health THE FUME LIMIT FOR CHROMIUM VI (0.05 MG/M*3) WILL BE REACHED BEFORE THE GENERAL LIMIT OF 5MG/M*3 FOR FUMES IS REACHED.MONITOR FUMES FOR CHROMIUM VI LEVEL.
=========== Physical/Chemical Properties ==========
HCC:N1 Appearance and Odor:WELDING ROD 0.125 INCHES DIAMETER BY 14 INCHES LONG.
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES

LDING ARCS & SPARKS CAN IGNITE

Hazardous Decomposition Products: FUMES OF METALS & METAL
OXIDES,CO,CO*2,NO*2,O*3,FLUORIDES.

======= Disposal Considerations ===========

Waste Disposal Methods:DISPOSE OF FUMES,FLUX OR WELD GRINDING RESIDUE IAW FEDERAL,STATE & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressl

y or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.