Product ID:MIL-L-8937,LUBRICANT,SOLID FILM,HEAT CURED MSDS Date:01/01/1985 FSC:9150 NIIN:00-834-5608 **MSDS Number: BFRSK** === Responsible Party === Company Name: ACHESON COLLOIDS CO Address:1600 WASHINGTON AVE Box:288 **City:PORT HURON** State:MI ZIP:48060-3456 Country:US Emergency Phone Num:313-984-5581 CAGE:70079 === Contractor Identification ===

Company Name:ACHESON COLLOIDS CO DIV OF ACHESON INDUSTRIES INC Address:1600 WASHINGTON AVE Box:611747 City:PORT HURON State:MI ZIP:48061-1747 Country:US Phone:800-255-3924 CAGE:70079

Ingred Name:TOLUENE (SARA III) CAS:108-88-3 RTECS #:XS5250000 OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:METHYL ALCOHOL (METHANOL) (SARA III) CAS:67-56-1 RTECS #:PC1400000 OSHA PEL:S ,200PPM/250STEL ACGIH TLV:S,200PPM/250STEL; 93 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:ETHYL ALCOHOL (ETHANOL) CAS:64-17-5 RTECS #:KQ6300000 OSHA PEL:1000 PPM ACGIH TLV:1000 PPM; 9192

LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER. Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:NONE SPECIFIED BY MANUFACTURER. Explanation of Carcinogenicity:THIS COMPOUND CONTAINS NO INGRE DIENTS AT CONCENTRATIONS OF 0.1% OR GREATER THAT ARE CARCINOGENS OR SUSPECT CARCINOGENS.

Effects of Overexposure:NONE SPECIFIED BY MANUFACTURER. Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

First Aid:EYES: FLUSH WITH WATER FOR 15 MINUTES WHILE HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN: REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSIST, GET MEDICAL

ATTENTION. INH ALATION: REMOVE TO FRESH AIR. RESTORE BREATHING. GET MEDICAL ATTENTION. INGESTION: GET MEDICAL ATTENTION.

Flash Point:46.0F,7.8C Lower Limits:NOT GIVEN Upper Limits:NOT GIVEN Extinguishing Media:NONE SPECIFIED BY MANUFACTURER. Fire Fighting Procedures:NONE SPECIFIED BY MANUFACTURER. Unusual Fire/Explosion Hazard:NONE SPECIFIED BY MANUFACTURER.

Spill Release Procedures: EVACUATE ALL UNPROTECTED PERSONNEL. EXTINGUISH ALL FLAMES IN THE VICINITY. CONTAIN SPILL AND SOAK UP ON INERT ABSORBENT MATERIAL. PLACE IN APPROPRIATE CONTAINERS AND AFFIX PROPER LABELS FOR DISPOSAL. Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

Handling and Storage Precautions:NONE SPECIFIED BY MANUFACTURER. Other Precautions:NONE SPECIFIED BY MANUFACTURER.

Respiratory Protection:NONE SPECIFIED BY MANUFACTURER. Ventilation:NONE SPECIFIED BY MANUFACTURER. Protective Gloves:NONE SPECIFIED BY MANUFACTURER. Eye Protection:NONE SPECIFIED BY MANUFACTURER. Other Protective Equipment:NONE SPECIFIED BY MANUFACTURER. Work Hygienic Practices:NONE SPECIFIED BY MANUFACTURER. Supplemental Safety and Health NONE SPECIFIED BY MANUFACTURER.

HCC:F2

Boiling Pt:B.P. Text:NOT GIVEN Melt/Freeze Pt:M.P/F.P Text:NOT GIVEN Vapor Pres:NOT GIVEN Vapor Density:NOT GIVEN Spec Gravity:NOT GIVEN Evaporation Rate & amp; Reference:NOT GIVEN Solubility in Water:NOT GIVEN Appearance and Odor:NOT GIVEN

NONE SPECIFIED BY MANUFACTURER. Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products:NONE SPECIFIED BY MANUFACTURER.

====== Disposal

Considerations =================

Waste Disposal Methods:PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. DISCARD ANY PRODUCT, RESIDUE, DISPOSAL CONTAINER OR LINER IN ACCORDANCE WITH ALL FEDERAL, STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this infor mation to be accurate and disclaims all liability for its use. Any person utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.