AIRCO WELDING PRODUCTS DIV OF THE BOC GROUP INC. -- CODE-ARC 7018 MR ELECTRODES -- 3439-00-853-2719

Product ID:CODE-ARC 7018 MR ELECTRODES MSDS Date:12/02/1985 FSC:3439 NIIN:00-853-2719 **MSDS Number: BHGBB** === Responsible Party === Company Name: AIRCO WELDING PRODUCTS DIV OF THE BOC GROUP INC. Address:4437 E 49TH STRRET City:CLEVELAND State:OH ZIP:44125-1005 Country:US Info Phone Num:216-641-8790 Emergency Phone Num:216-641-879 0 CAGE:83923 === Contractor Identification === Company Name: AIRCO WELDING PRODUCTS DIV OF THE BOC GROUP INC. Address:4437 E 49TH STRRET City:CLEVELAND State:OH ZIP:44125-1005 Country:US Phone:216-641-8790 CAGE:83923

Ingred Name:IRON CAS:7439-89-6 RTECS #:NO4565500 OSHA PEL:10 MG/M3(IRON OXIDE) ACGIH TLV:5 MG/M3 (IRON OXIDE)

Ingred Name:TITANIUM DIOXIDE CAS:13463-67-7 RTECS #:XR2275000 OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/ M3 TDUST; 9293

Ingred Name:SILICON CAS:7440-21-3 RTECS #:VW0400000 OSHA PEL:15 MG/M3 TDUST ACGIH TLV:10 MG/M3 TDUST; 9293

Ingred Name:MANGANESE (SARA III) CAS:7439-96-5 RTECS #:OO9275000 OSHA PEL:(C) 5 MG/M3 DUST ACGIH TLV:5 MG/M3 DUST 9293

Ingred Name:SODIUM SILICATE CAS:1344-09-8

Ingred Name:CALCIUM FLUORIDE CAS:7789-75-5 RTECS #:EW1760000 OSHA PEL:2.5 MG/M3 (F) ACGIH TLV:2.5 MG/M3 (F); 8990

Ingred Name:POTASSIUM TITANATE CAS:12030-97-6

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:SHORT TERM EXPOSURE TO WELDING FUMES, GASES OR DUST MAY RESULT IN DISCOMFORT SUCH AS DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT AND EYES. SKIN SENSITIVITY MAY ALSO BE NOTED. A CUTE EXPOSURE FROM SOME TOXIC GASES MAYCAUSE PULMONARY EDEMA, ASPHYXIATION AND EXCESSIVE EXPOSURE CAN BE FATAL.

Effec

ts of Overexposure:EXPOSURE TO WELDING FUMES MAY RESULT IN DISCOMFORT SUCH AS DIZZINESS, NAUSEA, FEVER, DRYNESS AND/OR IRRITATION OF NOSE, THROAT AND EYES. SKIN SENSITIVITY MAY ALSO BE NOTED. WATERY EYES, HEADACHE, BREA THING DIFFICULTY, FREQUENT COUGHING AND/OR CHEST PAINS MAY OCCURE FROM ACUTE EXPOSURE. TOXIC GASES CAN BE FATAL.

Medical Cond Aggravated by Exposure:SOME WORKERS MAY BE AFFECTED BY A PRE-EXISTING CONDITION OR OTHER OCCUPATIONAL ILLNESS BECAUSE OF THE W

IDE VARIATION IN INDIVIDUAL SUSCEPTIBILITIES.

First Aid:IN CASE OF ELECTRICAL SHOCK, TURN OFF POWER PRIOR TO REMOVAL FROM EXPOSURE AREA AND ADMINISTRATION OF FIRST AID. REMOVE FROM EXPOSURE AREA AND CALL FOR MEDICAL AID. ADMINISTER OXYGEN IF BREATHING IS D IFFICULT. IF NOT BREATHING, BEGIN ARTIFICIAL RESPIRATION. IF NO DETECTABLE PULSE, BEGIN EXTERNAL HEART MASSAGE. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY THE AMERICAN RED CROSS.

Flash Point:NONE

Extinguishing Media:NOT APPLICABLE;USE CARBON DIOXIDE, FOAM, DRY CHEMICAL, OR WATER FOG IN CASE OF SURROUNDING FIRE.
Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE.
Unusual Fire/Explosion Hazard:NON-FLAMMABLE. WELDING ARC AND SPARKS CA

Ν

IGNITE COMBUSTIBLES AND FLAMMABLE PRODUCTS.

Spill Release Procedures: CLEAN UP ANY GRINDING DUST OR WASTE RESIDUES AND PLACE IN SUITABLE DOT APPROVED CONTAINERS AND DISPOSE OF IN FULL COMPLIANCE WITH FEDERAL, STATE AND LOCAL REGULATIONS. AVOID INHALATION AND SKIN EXPOSU RE.

Handling and Storage Precautions:WEAR GLOVES AND FLAME RETARDANT

CLOTHING WHEN CUTTING, GRINDING OR WELDING. DO NOT EXPOSE SKIN TO RADIATION WHEN HOT CUTTING OR WELDING.

Other Precautions: PROVIDE PROTECTIVE SCREENS TO SHIELD OTHERS. WHEN ELECTRODES AND FLUXES ARE CONSUMED, THE FUME AND GAS DECOMPOSITION PRODUCTS GENERATED ARE DIFFERENT IN FORM FROM THE INGREDIENTS LISTED. NEW COMPOUNDS NOT IN THE ELECTRODES MAY FORM.

Respiratory Protection: USE WELD FUME RESPIRATOR OR AIR S

UPPLIED RESPIRATOR WHEN CUTTING, GRINDING OR WELDING IN A CONFINED SPACE OR WHERE LOCAL EXHAUST OR GENERAL VENTILATION DOES NOT KEEP EXPOSURE BELOW RECOMMENDED LIMITS. USE ONLY NIOSH APPROVED RESPIRATORS. Ventilation: USE ENOUGH VENTILATION WHEN CUTTING, GRINDING OR WELDING TO KEEP THE DUST, FUMES & GASES FROM THE WORKERS BREATHING ZONE Protective Gloves:WELDERS LEATHER GLOVES Eye Protection: OSHA APPROVED GOGGLES/FACE SHIELD W/LENS Other Protective Equipment: FLAME RETARDANT CLOTH ING WHEN CUTTING, GRINDING OR WELDING. DO NOT EXPOSE SKIN TO RADIATION WHEN HOT CUTTING OR WELDING. Work Hygienic Practices: WASH THOROUGHLY BEFORE EATING OR SMOKING. LAUNDER CONTAMINATIED CLOTHING BEFORE REUSE. Supplemental Safety and Health WELDING AND HOT CUTTING FUMES & GASES CANNOT BE CLASSIFIED SIMPLY. THEIR COMPOSITION AND QUANTITY ARE DEPENDENT ON THE METAL BEING WELDED, THE PROCEDURES, PROCESSES AND THE TYPE OF WIRE OR ELECTRODES USED. OTHER INFLUENCING FACTORS AR E THEPRESENCE OF CONTAMINANTS. CHLORINATED SOLVENTS MAY DECOMPOSE TO TOXIC GASES. HCC:N1 Solubility in Water: INSOLUBLE. Appearance and Odor: FLUX COATING ON A SOLID METAL CORE WIRE IN CUT LENGTHS. Stability Indicator/Materials to Avoid:YES NONE NOTED Stability Condition to Avoid:NONE NOTED Hazardous Decomposition Products:WELDING AND CUTTING OPERATIO N MAY INCLUDE OXIDES OF THE METALS, CHROMATES, FLUORIDES, COMPLEX METALLICS, AND OZONE.

Waste Disposal Methods: DISPOSE I/A/W FEDERAL, STATE & LOCAL REGULATIONS

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.