## 

Product ID:FLUX COATED SILVER ALLOY

MSDS Date:08/29/1988

FSC:3439

NIIN:00-956-4183

MSDS Number: BHYDB === Responsible Party ===

Company Name: AUFHAUSER BROTHERS CORPORATION

Address:39 WEST MALL

City:PLAINVIEW

State:NY

ZIP:11803-4209 Country:US

Info Phone Num:516-694-8695

Emergency Phone Num:516-694-8695

CAGE:59401

=== Contractor Identification ===

С

ompany Name: AUFHAUSER CORP

Address:39 WEST MALL Box:City:PLAINVIEW

State:NY

ZIP:11803-4209 Country:US

Phone:212-757-6824/FAX: 516-694-8690

CAGE:59401

======= Composition/Information on Ingredients ========

Ingred Name: SILVER (SARA III)

CAS:7440-22-4

RTECS #:VW3500000 Fraction by Wt: 55-60%

Other REC Limits: NONE SPECIFIED

OSHA PEL:0.01 MG/M3 ACGIH TLV:0.1 MG/M3; 9192

EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name: COPPER (SARA III)

CAS:7440-50-8

RTECS #:GL5325000 Other REC Limits: NONE SPECIFIED OSHA PEL:0.1MG/M3 FUME/1 DUST ACGIH TLV:0.2MG/M3 FUME; 9192

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:ZINC (SARA III)

CAS:7440-66-6

RTECS #:ZG8600000

Other REC Limits: NONE SPECIFIED

OSHA PEL:10 MG ZNO/M3

ACGIH TLV:10 MG ZNO/M3; 9192

EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name: NICKEL (SARA III)

CAS:7440-02-0

RTECS #:QR5950000

Other REC Limits: NONE SPECIFIED

OSHA PEL:1 MG/M3

ACGIH TLV:1 MG/M3; 9192

Ingred Name:CADMIUM (SARA III)

CAS:7440-43-9 RTECS #:EU98

00000

Other REC Limits: NONE SPECIFIED

OSHA PEL:SEE 1910.1027

ACGIH TLV:0.01 MG/M3 DUST;9394

EPA Rpt Qty:10 LBS DOT Rpt Qty:10 LBS

Ingred Name:TIN

CAS:7440-31-5

RTECS #:XP7320000

Other REC Limits: NONE SPECIFIED

OSHA PEL:2 MG/M3

ACGIH TLV:2 MG/M3; 9192

Ingred Name: POTASSIUM HYDROGEN FLUORIDE

CAS:7789-29-9

RTECS #:TS6650000

Other REC Limits: NONE SPECIFIED

OSHA PEL:2.5 MG/M3 (F)

ACGIH TLV:2.5 MG/M3 (F); 8990

Ingred Name: POTASSIUM TETRAFLUOBORATE

CAS:14075-53-7 RTECS #:ED2800000 Other REC Limits:N

## ONE SPECIFIED

Ingred Name: POTASSIUM BORATE

CAS:1332-77-0

Other REC Limits: NONE SPECIFIED

Ingred Name: POTASSIUM FLUORIDE

CAS:7789-23-3

RTECS #:TT0700000

Other REC Limits: NONE SPECIFIED

OSHA PEL:2.5 MG/M3 (F)

ACGIH TLV:2.5 MG/M3 (F); 8990

Ingred Name:BORIC ACID

CAS:10043-35-3 RTECS #:ED4550000

Other REC Limits: NONE SPECIFIED

Ingred Name:WATER CAS:7732-18-5

RTECS #:ZC0110000

Other REC Limits: NONE SPECIFIED

========== Hazards Identification =================

Routes of Entry: I

nhalation:YES Skin:NO Ingestion:NO

Health Hazards Acute and Chronic:FUMES AND GASES CAN BE DANGEROUS TO YOUR HEALTH. ARC RAYS CAN INJURE EYES AND BURN SKIN. ELECTRIC SHOCK CAN KILL. NOISE CAN DAMAGE HEARING.

Explanation of Carcinogenicity:NICKEL AND CADMIUM ARE LISTED UNDER IARC AND NTP.

Effects of Overexposure:ACUTE:METALLIC TASTE,NAUSEA,TIGHTNESS OF CHEST,FEVER,DIZZINESS,DRYNESS,IRRITATION OF EYES,NOSE AND THROAT. C

HRONIC:EXCESSIVE LEVELS MAY CAUSE BRONQUIAL ASTHMA, LUNG FIBROSIS AND PNEUMOCONIOSIS.

Medical Cond Aggravated by Exposure:AGGRAVATION OF EXISTING RESPIRATORY OR ALLERGIC CONDITIONS.HIGHER LEVEL OF LUNG RELATED PROBLEMS AMONG SMOKERS.

First Aid:REMOVE FROM EXPOSURE AND OBTAIN PROMPT MEDICAL ATTENTION. IF NOT BREATHING, GIVE CPR/OXYGEN. EMPLOY FIRST AID TECHNIQUES RECOMMENDED BY AMERICAN RED CROSS.

=======

======= Fire Fighting Measures ============
Extinguishing Media:AS APPROPIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE. Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS.
========= Accidental Release Measures ==========
Spill Release Procedures:CLEAN UP ANY GRINDING DUST OR WASTE RESIDUE AND PLACE IN APPROPIATE DISPOSAL CONTAINER.
======================================
Other Precautions:TRAIN WELDER TO KEEP HIS HEAD OUT OF THE FUMES.MONITOR AIR TO ENSURE ACCEPTABLE EXPOSURES.AVOID ELECTRICAL SHOCK BY MAINTAINING DRY WORK AREA. WELDING ARC CAN IGNITE COMBUSTIBLES AND FLAMMABLES.
====== Exposure Controls/Personal Protection ========
Respiratory Protection: FUME RESPIRATOR OR AIR SUPPLIED RESPIRATOR IN CONFINED SPACES OR WHERE VENTILATION DOES NOT KEEP EXPOSURE BELOW TLV.
Ventilation:LOCAL EXHAUST TO KEEP BELOW TLV. Protective Gloves:WELDER'S GLOVES. Eye Protection:HELMET OR FACE SHIELD WITH FILTER LENS. Other Protective Equipment:SUBSTANTIAL DARK CLOTH,ARM PROTECTOR,APRON,HAT AND SHOULDER PROTECTION. Work Hygienic Practices:WASH HANDS THOROUGHLY BEFORE EATING,SMOKING OR USING SANITARY FACILITIES. Supplemental Safety and Health NONE
======================================
HCC:N1 Solubility in Water:INSOLUBLE Appearance and Odor:METALLIC ROD OR WIRE.
========= Stability and Reactivity Data ==========
Stability Indicator/Materials to Avoid:YES NONE. Stability Condition to Avoid:NONE. Hazardous Decomposition Products:FUMES OF METALS AND METAL OXIDES, HYDROFLUORIC ACID, FLUORIDES, CARBON MONOXIDE, CARBON DIOXIDE,
OZONE, NITROGEN OXIDES.  ======== Disposal

Considerations ==========

particular situation.

Waste Disposal Methods:CONSULT WITH YOUR LOCAL ENVIRONMENTAL OFFICER.DISPOSE OF FUMES,FLUX OR WELD GRINDING RESIDUE FROM THE WORK AREA OR FROM FILTERS IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL ENVIRONMENTAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their