Product ID:ALLOSPERSE UD 3D RAW UMBER

MSDS Date:07/01/1987

FSC:8010

NIIN:00-598-7439
MSDS Number: BJLJB
=== Responsible Party ===

Company Name: SILVERTOWN PRODUCTS, INC.

Address:863 WEST HOLT BLVD.

City:ONTARIO

State:CA ZIP:91761 Country:US

Info Phone Num:714-986-7061

Emergency Phone Num:714-985-2306

CAGE:60137

=== Contractor Identification ===

Company

Name: SILVERTOWN PRODUCTS INC

Address:863 W HOLT BLVD

Box:443

City:ONTARIO

State:CA

ZIP:91761-1853 Country:US CAGE:60137

======= Composition/Information on Ingredients ========

Ingred Name:MINERAL SPIRITS (VP 5 MMHG @ 77F) (TOXICITY DATA: LD 50 (RABBIT) GREATER THAN 19.9 G/KG)

CAS:64742-48-9

Fraction by Wt: >10-19.9 G/KG (RABBIT)

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ACUTE I

NHALATION: IRRITATION OF THE

NOSE, THROAT AND EYES, POSSIBLY HEADACHE AND NAUSEA. LIQUID IS IRRITATING TO EYES. IF SWALLOWED GIVE TWO GLASSES OF WATER, INDUCE VOMITING, CALL PHYSICIAN. CHRONIC RESPIRATORY IRRITATION MAY OCCUR.

Explanation of Carcinogenicity:NO

Effects of Overexposure:ACUTE INHALATION: IRRITATION OF THE NOSE, THROAT AND EYES, POSSIBLY HEADACHE AND NAUSEA. LIQUID IS IRRITATING TO EYES. IF SWALLOWED GIVE TWO GLASSES OF WATER, INDUCE VOMITING, CALL PHYSI

CIAN. CHRONIC RESPIRATORY IRRITATION MAY OCCUR.
======================================
First Aid:REMOVE PATIENT TO FRESH AIR. REMOVE SATURATED CLOTHING. FLUSH EYES WITH CLEAN WATER FOR 15 MINUTES. WASH SKIN THOROUGLY. IF SYMPTOMS PERSIST, SEEK MEDICAL ATTENTION.
======================================
Flash Point:>125 F/>52 C Extinguishing Media:FOAM, CO2, DRY CHEMICAL, WATER FOG, SPRAY Fire Fighting Procedures:FIGHT AS VOLA TILE LIQUID FIRE - USE WATER TO KEEP FIRE EXPOSED CONTAINERS COOL - TO REDUCE PRESSURE. Unusual Fire/Explosion Hazard:DO NOT ENTER ANY ENCLOSED OR CONFINED FIRE SPACE WITHOUT PROPER PROTECTIVE EQUIP & SELF CONTAINED BREATHING APPARATUS. KEEP AWAY FROM HEAT, SPARKS & OPEN FLAME.
======== Accidental Release Measures =========
Spill Release Procedures:SOAK UP WITH INERT ABSORBENT AND PLACE IN CONTAINER FOR DISPOSAL.
======================================
Handling and Storage Precautions:AVOID CONTACT WITH SKIN & EYES. WASH YOURSELF THOROUGHLY IF YOU DO COME IN CONTACT. KEEP CONTAINER CLOSED. PROTECT FROM FREEZING. KEEP AWAY FROM FOOD. Other Precautions:DO NOT BREATH SPRAY MIST. AVOID SPONTANEOUS COMBUSTION OF CONTAMINATED RAGS & OTHER EASILY IGNITABLE ORGANIC ACCUMULATIONS (SUCH AS SPRAY RESIDUE) BY IMMERSION IN WATER. DO NOT PUNCTURE OR WELD EMPTY CONTAINERS OR WELD NEAR SAME.
====== Expos ure Controls/Personal Protection =========
Ventilation:GENERAL Protective Gloves:RUBBER OR NEOPRENE GLOVES Eye Protection:CHEMICAL GOGGLES Other Protective Equipment:NEOPRENE OR RUBBER APRON Supplemental Safety and Health
========== Physical/Chemical Properties ==========
HCC:F4 Boiling Pt:B.P. Text:310 TO 370F Vapor Density:< THAN AIR Evaporation Rate & Description Rate & Percent Volatiles by Volume:38
========== Stability and Reactivity Data ===

==========

Stability Indicator/Materials to Avoid:YES STRONG OXIDANTS Hazardous Decomposition Products:USUAL PRODUCTS OF COMBUSTION CO AND CO2.

======= Disposal Considerations ===========

Waste Disposal Methods:PLACE IN CLOSED CONTAINERS. INCINERATE (FIRST OPEN CLOSED CONTAINER) OR USE SECURE LANDFILL IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is for mulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.