Product ID:EA 9396 PART B

MSDS Date:09/29/1989

FSC:8040

NIIN:00-209-1286

Kit Part:Y

MSDS Number: BLJSH === Responsible Party ===

Company Name: DIAL CORP THE

Address:1865 DIAL TOWER

Box:312

City:PHOENIX

State:AZ

ZIP:85077-1865 Country:US

Info Phone Num:602-991-3000

Emergency Phone Num:602-991-3000 Preparer's Name:SUZANNE FRANZ

CAGE:0EK45

=== Contractor Identification ===

Compa

ny Name: DEXTER CORPORATION ADHESIVE & COATING SYSTEMS

Address:2850 WILLOW PASS ROAD

Box:312

City:BAY POINT

State:CA

ZIP:94565-3299 Country:US

Phone:202-483-7616

CAGE:33564

Company Name: DIAL CORP THE Address: 111 W CLARENDON AVE

Box:3223 City:PHOENIX State: 4.7

State:AZ ZIP:85077 Country:US

Phone:602-991-3000

CAGE:0EK45

======= Composition/Information on Ingredients ========

Ingred Name: ALKYLAMINES

Fraction by Wt: 149C

Extinguishing Media: DRY CHEMICAL, HALON FIRE EXTINGUISHER, WATER SPRAY,

======= Disposal Considerations ==========
HCC:B2 Boiling Pt:B.P. Text:644F,340C Vapor Pres:1 LB. DO NOT HEAT MIXED ADHESIVE UNLESS CURING SURFACES TO BE BONDED.
========= Physical/Chemical Properties ==========
VENTILATION. DO NOT CUT OR WELD CONTAINER.
AVOID BREATHING VAPORS. KEEP CONTAINER CLOSED. U SE ONLY WITH GOOD
KEY1:C2. CAUSES IRRITATION TO SKIN AND EYES. CONTAINS TETRAETHYLENEPENTAMINE. AVOID CONTACT. VAPORS MAY BE IRRITATING.
HAS BEEN READ AND UNDERSTOOD. Supplemental Safety and Health
Other Protective Equipment: AS NEEDED TO PROTECT SKIN AND CLOTHING. Work Hygienic Practices: WASH AFTER HANDLING. DO NOT USE UNTIL THE MSDS
Protective Gloves:IMPERVIOUS PLASTIC OR RUBBER. Eye Protection:SAFETY GLASSES OR GOGGLES.
Ventila tion:LOCAL EXHAUST RECOMMENDED.
Respiratory Protection:NOT NEEDED WITH GOOD INDUSTRIAL VENTILATION.
====== Exposure Controls/Personal Protection ========
Other Precautions:FAILURE TO OBSERVE CAUTION MAY RESULT IN EXCESSIVE HEAT BUILD-UP WITH THE RELEASE OF TOXIC GASES.
INSTRUCTIONS. STORE AT ROOM TEMPERATURE (77 DEG. F) FOR 12 MONTHS. FOLLOW RECOMMENDED CURING SCHEDULE.
Handling and Storage Precautions:KEEP COOL IN ACCORDANCE WITH LABEL
====== Handling and Storage ===========
Spill Release Procedures:WEAR PROTECTIVE CLOTHING, GLOVES AND SAFETY GLASSES. SCRAPE UP AND TRANSFER TO METAL CONTAINER. WIPE UP REMAINING RESIDUE WITH SOLVENTS, OBSERVING SOLVENT FLAMMABILITY CAUTIONS.
======== Accidental Release Measures ==========
Unusual Fire/Explosion Hazard:DENSE SMOKE AND TOXIC GASES MAY BE LIBERATED.
Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS WHEN FIGHTING FIRES IN CONFINED AREAS.
FOAM OR FOG.

Disclaimer (provided with this information by the compiling ag

Waste Disposal Methods:DISPOSE OF AS HAZARDOUS WASTE ACCORDING TO LOCAL, STATE & FEDERAL REGULATIONS.

encies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.