Product ID: TUNGSTEN WELDING ELECTRODES MSDS Date:08/01/1991 FSC:3439 NIIN:00-132-6710 **MSDS Number: BPDXQ** === Responsible Party === Company Name: TELEDYNE MCKAY Address:850 GRANTLEY RD Box:1509 City:YORK State:PA ZIP:17405 Country:US Info Phone Num:717-849-2455 FAX:717-849-2365 Emergency Phone Num:717-845-7581 CAGE:76254 === Contractor Identification === Company Name: HOBART BROS CO MCKAY WELDING PRODUCTS DIV Address:400 TRADE SQ E Box:City:TROY State:OH ZIP:45373-2900 Country:US Phone:513-332-5706 CAGE:76254 Company Name: YORK WELDING SUPPLY INC Address:2609 N GEORGE ST Box:City:YORK State:PA ZIP:17402-1018 Country:US CAGE:6L121

Ingred Name:TUNGSTEN CAS:7440-33-7 RTECS #:YO7175000 Fraction by Wt: >99% Other REC Limits:NONE RECOMMENDED OSHA PEL:5 MG/M3/ 10 STEL ACGIH TLV:5 MG/M3/10 S TEL;9293

Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ACUTE: INHALATION OF WELDING FUMES MAY CAUSE NERVOUS SYSTEM AND MUSCLE IRREGULARITIES, IRRITATION OF EYES, NOSE, THROAT, AND RESPIRATORY SYSTEM, METAL FUME FEVER. CHRONIC: INHALATION OF FUMES MAY AFFE CT LUNG FUNCTION.

Explanation of Carcinogenicity:NONE

Effects of O

verexposure:INHALATION: NAUSEA, DIZZINESS, DRYNESS OF NOSE AND THROAT, COUGHING, WHEEZING AND SHORTNESS OF BREATH. EYES: REDNESS, TEARING, BLURRED VISION.

Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

First Aid:INHALATION: REMOVE TO FRESH AIR. RESUSCITATE IF NEEDED. EYES: FLUSH WITH PLENTY OF WATER FOR 15 MINUTES. SEE DOCTOR. SKIN: WASH WITH SOAP AND WATER. INGESTION: DO NOT INDUCE VOMITI NG. SEE DOCTOR.

Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:WEAR SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE GEAR.

Unusual Fire/Explosion Hazard:WHEN TUNGSTEN IS HEATED IN AIR, TUNGSTEN TRIOXIDE BEGINS TO SUBLIME ABOVE 750F.

Spill Release Procedures: PICK UP RODS. SWEEP UP OR MOP. PLACE RESIDUE IN A CONTAINER FOR DISPOSAL. Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

Handling and Storage Precautions:REMOVE ANY COMBUSTIBLES FROM WORK AREA: SPARKS OR WELDING ARC COULD IGNITE NEARBY COMBUSTIBLES. Other Precautions:NONE SPECIFIED BY MANUFACTURER.

====== Exposure Controls/Personal Protection ==========

Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR FOR WELDING FUMES OR SUPPLIED A

IR RESPIRATOR IN CONFINED SPACES OR WHERE FUME CONCENTRATION EXCEEDS REGULATORY LIMITS. Ventilation:USE MECHANICAL OR LOCAL EXHAUST OR BOTH TO MAINTAIN LEVELS OF FUMES BELOW REGULATORY LIMITS. Protective Gloves:WELDERS WORK GLOVES Eye Protection:WELDERS HELMET WITH CORRECT LENSES Other Protective Equipment:CLOTHING TO PROTECT ENTIRE BODY FROM SPARKS. Work Hygienic Practices:WASH HANDS AFTER USE AND BEFORE EATING, DRINKING, OR SMOKING. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. Suppl emental Safety and Health

HCC:N1 Boiling Pt:B.P. Text:6152F,3400C Spec Gravity:19 Solubility in Water:INSOLUBLE Appearance and Odor:TIN-WHITE METAL, NO ODOR

Stability Indicator/Materials to Avoid:YES NONE SPECIFIED BY MANUFACTURER. Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products:METAL FUMES, FLUORIDES, OXIDES AN D

OTHER HAZARDOUS MATERIALS.

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liabilit

y for its use. Any person utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.