KESTER SOLDER COMPANY DIV OF LITTON SYSTEMS INC -- #44 RESIN CORE SOLDER 3439-00-452-0374

Product ID:#44 RESIN CORE SOLDER

MSDS Date:12/12/1988

FSC:3439

NIIN:00-452-0374

MSDS Number: BQDKP === Responsible Party ===

Company Name: KESTER SOLDER COMPANY DIV OF LITTON SYSTEMS INC

Address:515 E TOUHY City:DES PLAINES

State:IL

ZIP:60018-2675 Country:US

Info Phone Num:708-297-1600

Emergency Phone Num:312-297-1600

CAGE:09185

=== Co

ntractor Identification ===

Company Name: KESTER SOLDER COMPANY

Address:515 E. TOUHY AVENUE

Box:City:DES PLAINES

State:IL ZIP:60018 Country:US

Phone:800-424-9300

CAGE:09185

Company Name: KESTER SOLDER DIVISION OF LITTON SYSTEMS, INC.

Address:515 E. TOUHY AVENUE

Box:City:DES PLAINES

State:IL ZIP:60018 Country:US

Phone:847-297-1600

CAGE:75297

======= Composition/Information on Ingredients ========

Ingred Name: ROSIN ACID

CAS:8050-09-7 Fraction by Wt: 95%

Other REC Limits: NONE RECOMMEND

ED
========= Hazards Identification ===========
Routes of Entry: Inhalation:YES Skin:NO Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:SMOKE DURING SOLDERING CAN IRRITATE EYES AND RESPIRATORY TRACT. FLUX FUMES MAY CAUSE PULMONARY IRRITATION AND LUNG DAMAGE. Explanation of Carcinogenicity:THIS COMPOUND CONTAINS NO INGREDIENTS AT
CONCENTRATIONS OF 0.1% OR GREATER THAT ARE CARCINOGENS OR SUSPECT CARCINO GENS.
Effects of Overexposure:ROSIN IS AN ALLERGEN - MAY CAUSE RASH, HEADACHE, OR THROAT IRRITATION IN A SENSITIVE PERSON. Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.
======================================
First Aid:EYES CONTACT: FLUSH THOROUGHLY WITH WATER AND GET MEDICAL ATTENTION. SKIN CONTACT: WASH WITH SOAP AND WATER. INHALATION: REMOVE TO FRESH AIR. INGESTION: N/A.
======================================
Flash Point Method:COC Flash Point:420F,216C Extinguishing Media:CARBON DIOXIDE, ALCOHOL FOAM, OR DRY CHEMICAL. Fire Fighting Procedures:NONE Unusual Fire/Explosion Hazard:NONE
============ Handling and Storage =============
Handling and Storage Precautions:AVOID EYE CONTACT WITH HOT FLUX. AVOID BREATHING SMOKE DURING SOLDERING. WASH HANDS BEFORE EATING OR SMOKING AFTER HANDLING SOLDER WIRE. Other Precautions:DO NOT PLACE FLUX CORED SOLDER WIRE INTO A HOT SOLDER POT. THE FLUX MAY IGNITE.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USUALLY NOT REQUIRED. Ventilation:LOCAL EXHAUST: REMOVE SMOKE FROM BREATHING AREA. MECHANICAL(GENERAL): RECOMMENDED. Protective Gloves:NONE REQUIRED. Eye Protection:SAFETY GLASSES. Other Protective Equipment:NONE. Work Hygienic Practices:WASH THOROUGHLY AFTER HANDLING AND BEFORE EATING, DRINKING OR SMOKING. Supplemental Safety and Health NONE

Spec Gravity:1.08 Solubility in Water:INSOLUBLE Appearance and Odor:SOLID AMBER CORE INSIDE SOLDER WIRE.
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES STRONG OXIDIZERS. Stability Condition to Avoid:NONE SPECIFIED BY MANUFACTURER. Hazardous Decomposition Products:SMALL AMOUNTS OF TURPENTINE. MAY EMIT HYDROGEN CHLORIDE FUMES (

==== Physical/Chemical Properties ========

HCC:N1