

HENTZEN COATINGS, INC -- OFF-WHITE PRIMER PAINT MIL-P-53022B TYPE 1 05510WEP-X PART A
-- 8010-01-193-0517

===== Product Identification =====

Product ID:OFF-WHITE PRIMER PAINT MIL-P-53022B TYPE 1 05510WEP-X PART A

MSDS Date:06/16/1994

FSC:8010

NIIN:01-193-0517

Kit Part:Y

MSDS Number: BVVDC

=== Responsible Party ===

Company Name:HENTZEN COATINGS, INC

Address:6937 W MILL ROAD

City:MILWAUKEE

State:WI

ZIP:53218

Country:US

Info Phone Num:414-353-4200

Emergency Phone Num:414-353-4200/800-424-9300 CHEMTREC

Preparer's Name:JANE FREEMAN

CAGE:09225

=== Contractor Identification ===

Company Name:HENTZEN COATINGS INC

Address:6937 WEST MILL ROAD

Box:18749

City:MILWAUKEE

State:WI

ZIP:53218

Country:US

Phone:414-353-4200

CAGE:09225

===== Composition/Information on Ingredients =====

Ingred Name:TITANIUM DIOXIDE (PIGMENT)

CAS:13463-67-7

RTECS #:XR2275000

Fraction by Wt: 15-20%

Other REC

Limits:NONE RECOMMENDED

OSHA PEL:10 MG/M3

ACGIH TLV:10 MG/M3

Ingred Name:TALC (PIGMENT)

CAS:14807-96-6

RTECS #:WW2710000

Fraction by Wt: 15-20%

Other REC Limits:NONE RECOMMENDED

OSHA PEL:2 MG/M3

ACGIH TLV:2 MG/M3

Ingred Name:1-METHOXY-2-PROPANOL (SOLVENT)

CAS:107-98-2

RTECS #:UB7700000

Fraction by Wt: 15.789%

Other REC Limits:STEL: 150 PPM

OSHA PEL:100 PPM

ACGIH TLV:100 PPM

Ingred Name:METHYL AMYL KETONE (SOLVENT)

CAS:110-43-0

RTECS #:MJ5075000

Fraction by Wt: 1.511%

Other REC Limits:NONE RE
COMMENDED

OSHA PEL:100 PPM

ACGIH TLV:50 PPM

Ingred Name:BUTYL ALCOHOL (SOLVENT) (SARA III)

CAS:71-36-3

RTECS #:EO1400000

Fraction by Wt: 9.606%

Other REC Limits:(SKIN NOTATION)

OSHA PEL:50 PPM (CEILING)

ACGIH TLV:50 PPM (CEILING)

EPA Rpt Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name:METHYL ETHYL KETONE (SOLVENT) (2-BUTANONE) (SARA III)

CAS:78-93-3

RTECS #:EL6475000

Fraction by Wt: 4.965%

Other REC Limits:STEL: 300 PPM

OSHA PEL:200 PPM

ACGIH TLV:200 PPM

EPA Rpt Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name:EPOXY RESIN
Fraction by Wt: 20-30%
Other REC Limits:NONE RECOMMENDED

Ingred Name:ZINC (METAL) (SARA III)
CAS:7440-66-6
RTECS #:ZG8600000
Fraction by Wt: 1.694%
Other REC Limits:NUISANCE DUST
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:XYLENE (SOLVENT) (SARA III)
CAS:1330-20-7
RTECS #:ZE2100000
Fraction by Wt: 5.449%
Other REC Limits:STEL: 150 PPM
OSHA PEL:100 PPM
ACGIH TLV:100 PPM
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:VOC: 4.245 LBS/GAL 508.678 GRAMS/L
ITER
RTECS #:9999999VO
Other REC Limits:NONE RECOMMENDED

===== Hazards Identification =====

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:INHAL: ANESTHETIC. RESP TRACT IRRIT,
ACUTE NERVOUS SYS DEPRESS
(HEADACHE,DIZZINESS,STAGGERING,CONFUSION,COMA). SKIN/EYE:
IRRITATION. CHRONIC OVEREXPOSURE: REPORTS ASSOCIATE REPEATED &
PROLONGED OVEREX POSURE W/PERMANENT BRAIN & NERVOUS SYSTEM DAMAGE,
LIVER AND KIDNE
Y DAMAGE.
Medical Cond Aggravated by Exposure:ASTHMA AND OTHER RESPIRATORY
AILMENTS; CHEMICAL SENSITIZATION.

===== First Aid Measures =====

First Aid:INHALATION: REMOVE FROM EXPOSURE. RESTORE BREATHING. KEEP
WARM AND QUIET. NOTIFY A PHYSICIAN. EYES: FLUSH IMMEDIATELY WITH
LARGE AMOUNTS OF RUNNING WATER FOR AT LEAST 15 MINUTES. TAKE TO A
PHYSICIAN F OR MEDICAL TREATMENT. SKIN: WASH AFFECTED AREA WITH
SOAP AND WATER. REMOVE CONTAMINATED C

NOTHING. CONSULT A PHYSICIAN.

INGESTION: CALL PHYSICIAN OR POISON CONTROL CENTER IMMEDIATELY.

===== Fire Fighting Measures =====

Flash Point Method:TCC

Flash Point:21.0F,-6.1C

Autoignition Temp:Autoignition Temp Text:532 F

Lower Limits:1.1

Upper Limits:36.5

Extinguishing Media:FOAM, DRY CHEMICAL, CO2

Fire Fighting Procedures:FULL PROTECT EQUIP W/SCBA.WATER SPRAY MAY BE INEFFECTIVE,USE TO COOL (FOG NOZZLES PREFERRED)CLOSED CONTAINER TO PREVENT PRESSU

RE BLDUP,AUTOIGNITION OR EXPLOSION.

Unusual Fire/Explosion Hazard:KEEP CNTNR CLSD.KEEP FROM HEAT,IGNIT

SOURCE.CLSD CNTNR MAY EXPLODE W/HEAT.DON'T APPLY TO HOT

SURFACE.NEVER USE WELD/CUT TORCH ON/NEAR DRUM (EVEN EMPTY)-EXPLODE.

===== Accidental Release Measures =====

Spill Release Procedures:REMOVE ALL SOURCES OF IGNITION (FLAMES, HOT SURFACES AND ELECTRICAL, STATIC OR FRICTIONAL SPARKS). AVOID BREATHING VAPORS. VENTILATE AREA. CONTAIN AND REMOVE WITH INERT ABSORBENT AND NONSPARKING TOOLS .

===== Handling and Storage =====

Handling and Storage Precautions:DO NOT TAKE INTERNALLY. CONTAINERS SHOULD BE GROUNDED WHEN POURING. AVOID FREE FALL OF LIQUID IN EXCESS OF A FEW INCHES. DO NOT STORE ABOVE 120F.

Other Precautions:STORE LRG QTY IN BLDGS IN COMPLIANCE W/OSHA 1910.106. KEEP AWAY FROM SPARKS & OPEN FLAME. USE W/VENT & RESPRTRY EQUIP. AVOID SKIN CONTACT. EMPTY CNTNRS RETAIN HZD RESIDUE/EXPLOSIVE VAPOR. FOLLOW PRECAUTIONS UNTIL CNTNR CLEANED OR DESTROYED.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:IN OPEN AREA DURING SAND/GRINDING,USE NIOSH MECHAN FILTER RESPRTR.IN RESTRICTD VENT,WEAR NIOSH CHEM/MECHAN FILTER.IN CONFINED AREA,WEAR NIOSH AIR SUPPLD RESPRTR/HOOD.USE NIOSH RESPRTR WHEN FLAME CUT/WELDING OR HAZING MAT'L W/PRODUCT.

Ventilation:PROVIDE GENERAL DILUTION OR LOCAL EXHAUST VENT TO KEEP AIR CONTAMINANT C

ONCENTRATION BELOW OSHA PEL & REMOVE DECOMP PROD
Protective Gloves:REQUIRED FOR PROLONGED/REPEATED CONTACT.
Eye Protection:SAFETY EYEWEAR W/SPLASH GUARD/SIDE SHLD
Other Protective Equipment:USE PROTECTIVE SKIN CREAM WHERE CONTACT IS
LIKELY. PREVENT PROLONGED SKIN CONTACT WITH CONTAMINATED CLOTHING.
Work Hygienic Practices:WASH CONTAMINATED CLOTHING BEFORE REUSE. WASH
HANDS BEFORE EEATING OR SMOKING. SMOKE IN DESIGNATED AREAS ONLY.
Supplemental Safety and Health

===== Physi
cal/Chemical Properties =====

Boiling Pt:B.P. Text:170 TO 305F
Decomp Temp:Decomp Text:400F,204C
Vapor Pres:74.00@ 68F
Vapor Density:> AIR
Spec Gravity:1.33
Viscosity:63 - 73 KU
Evaporation Rate & Reference:FASTER THAN BUTYL ACETATE
Solubility in Water:NEGLIGIBLE
Appearance and Odor:OPAQUE LIQUID, SOLVENT ODOR
Percent Volatiles by Volume:59.07

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES
STRONG OXIDIZERS
Hazar
dous Decomposition Products:MAY PRODUCE HAZARDOUS FUMES WHEN
HEATED TO DECOMPOSITION AS IN WELDING. FUMES MAY CONTAIN CARBON
MONOXIDE & DIOXIDE.

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH LOCAL, STATE, AND
FEDERAL REGULATIONS. DO NOT INCINERATE CLOSED CONTAINERS.
INCINERATE IN AN APPROVED FACILITY. EPA HAZARDOUS WASTE CODE: D001,
IGNITABLE.

=====

=====

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.