OEA AEROSPACE INC. -- 20804-1099 SMDC SHIELDED MILD DETONATING CORD 1377-00-167-8420

Product ID:20804-1099 SMDC SHIELDED MILD DETONATING CORD MSDS Date:12/21/1995 FSC:1377 NIIN:00-167-8420 MSDS Number: CDSVH === Responsible Party === Company Name: OEA AEROSPACE INC. Address: HWY 12 AND ET RD Box:KK City:FAIRFIELD State:CA ZIP:94533-0659 Country:US Info Phone Num:707-422-1880 Emergency Phone Num:707-422-1880 Preparer's Name:S SCHOOLFIELD/J KOHRING CAGE:17610 === Contractor Identification === Company Name: OEA AEROSPACE INC Address:3530 BRANSCOMBE RD Box:KK City:FAIRFIELD State:CA ZIP:94533-0659 Country:US Phone:707-422-1880 CAGE:17610

Ingred Name:X-CHORD, 2.5 GRAINS/FT, SILVER SHEATH ACGIH TLV:0.1 MG/CUM

Ingred Name:HEXANITROSTILBENE I ACGIH TLV:10.0 MG/CUM

Routes of Entry: In

 halation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHALATION: IRRITATION TO THE NOSE, THROAT & MUCOUS MEMBRANE, ALLERGIC REACTIONS. SKIN: IRRITATION & ABSORPTION, ALLERGIC REACTIONS. EYES: IRRITATION. INGESTION: TOXIC, MAY CAUSE DEATH. Explanation of Carcinogenicity:NONE Effects of Overexposure:IRRITATION, NAUSEA, REDNESS.
======================================
First Aid:EYES: FL USH W/WATER FOR 15 MINS. SKIN: WASH W/SOAP & WATER. INHALATION: REMOVE TO FRESH AIR. OBTAIN MEDICAL ATTENTION IN ALL CASES.
======================================
Fire Fighting Procedures:DON'T ATTEMPT TO EXTINGUISH. EVACUATE AREA. USE SCBA TO CONTAIN RESULTING FIRE. Unusual Fire/Explosion Hazard:IF EXPOSED TO FIRE, THE UNIT MAY ACTUATE/EXPLODE.
======================================
Spill Release Procedures:CALL LOCA L HAZARDOUS MATERIALS TEAM. REMOVE IGNITION SOURCES. COVER ANY EXPOSED MATERIAL W/VEGETABLE OIL & REMOVE FOR APPROVED DISPOSAL. USE FLAME RETARDANT CLOTHING, SAFETY GLASSES & NON-SPARKING TOO LS.
======================================
Handling and Storage Precautions:ANTI-STATIC ARE TO BE USED FOR STORAGE & SHIPPING. Other Precautions:THIS MSDS ISN'T INTENDED TO BE AN ORDNANCE HANDLING DOCUMENT.
======================================
Respiratory Protection:USE A NIOSH APPROVED HEPA RESPIRATOR IF PEL/TLV IS EXCEEDED. Ventilation:LOCAL EXHAUST: REQUIRED FOR TEST FIRING. Protective Gloves:POLY-BENZ IMMIDAZOLE/LEATHER FOR CLEANUP Eye Protection:SAFETY GLASSES AS A MINIMUM Other Protective Equipment:FLAME RETARDANT COAT & GROUNDING STRAPS TO PREVENT ELECTROSTATIC DISCHARGE. Supplemental Safety and Health

Solubility in Water:INSOLUBL

E Appearance and Odor:SMDC: SILVER; ODORLESS

Stability Indicator/Materials to Avoid:YES
ALKALIS, ACIDS, BRONZE, CORROSIVES & OXIDIZERS.
Stability Condition to Avoid:MECHANICAL SHOCK, STATIC ELECTRICITY, HEAT, FLAME/SPARKS.
Hazardous Decomposition Products:CO, NITROGEN, NITROUS OXIDES, HYDROGEN, CARBON, CO2 & WATER.

Waste Disposal Methods:UNFIRED UNIT S/WASTE SHOULD BE DISPOSED AS REACTIVE (D003) & TOXIC (D011) HAZARDOUS WASTE, IAW/FEDERAL, STATE & LOCAL REGULATIONS. UN-0367.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.