View NSN Online: https://aerobasegroup.es/nsn/6830-01-303-4937

## C F C RECLAIMATION AND RECYCLING SERVICE INC -- HEXANE -- 6830-01-303-4937

Product ID:HEXANE MSDS Date:01/01/1995

FSC:6830

NIIN:01-303-4937 Status Code:A

MSDS Number: CHZBR === Responsible Party ===

Company Name: C F C RECLAIMATION AND RECYCLING SERVICE INC

Address:318 N TREADAWAY

Box:560

City:ABILENE

State:TX ZIP:79604 Country:US

Info Phone Num:9150-675-5311 FAX:

915-675-5324

Emergency Phone Num:9150-675-5311 FAX: 915-675-5324

CAGE:0XXK5

=== Contractor Identification ===

Company Name: C F C RECLAIMATION AND RECYCLING SERVICE INC

Address:318 N TREADAWAY

Box:560 City:ABILENE State:TX

ZIP:79604 Country:US

Phone:9150-675-5311 FAX: 915-675-5324

CAGE:0XXK5

======= Composition/Information on Ingredients ========

Ingred Name: HEXANE (N-HEXANE) (CERCLA)

CAS:110-54-3

RTECS #:MN9275000 Fraction by Wt: 100%

Other REC Limits: NONE RECOMMENDED

**OSHA PEL:50** 

0 PPM ACGIH TLV:50 PPM; 9596 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB LD50 LC50 Mixture:OSHA 1993 PEL (8HR TWA)=500 MOLAR PPM Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic: CAUSES HARM TO THE NERVOUS SYSTEM WHICH PRODUCES A LACK OF FEELING IN THE EXTREMITIES AND OTHER NERVE DAMAGE. IT CAN BE ABSORBED THROUGH THE SKIN IN HARMFUL AM Explanation of Carcinogenicity: HEXANE IS NOT LISTED IN THE IARC, NTP OR BY OSHA AS A CARCINOGEN OR POTENTIAL CARCINOGEN. Effects of Overexposure: INHALATION OF THE VAPOR CAUSES DIZZINESS, DIFFICULTY IN WALKING, RESPIRATORY TRACT IRRITATION, NUMBNESS OF THE EXTREMETIES, AND EVENTUAL PARALYSIS. IT IS AN IRRITANT TO THE SKIN AND EYES. Medical Cond Aggravated by Exposure: PERSONS IN ILL HEALTH WHERE SUCH ILLNESS WOULD BE AGGRAVATED BY EXPOSURE TO HEXANE SHOULD NOT BE ALL OWED TO WORK WITH OR HANDLE THIS PRODUCT. First Aid:PROMPT MEDICAL ATTENTION IS MANDATORY IN ALL CASES. INHALATION-CONSCIOUS PERSON SHOULD BE ASSISTED TO AN UNCONTAMINATED AREA & INHALE FRESH AIR. QUICK REMOVAL IS IMPORTANT. UNCONSCIOUS PERSON SHOULD B E REMOVED, GIVEN ASSISTED RESPIRATION & SUPPLEMENTAL OXYGEN. EYE-FLUSH WITH COPIUS QUANTITIES OF WATER. CONTINUE FOR 15 MIN. SKIN-FLUSH AREAS WITH COPIOUS AM **OUNTS OF WATER. REMOVE** CLOTHING RAPIDLY. ============= Fire Fighting Measures ======================== Flash Point:-7F,-22C Lower Limits:1.7

**Upper Limits:7.7** 

Extinguishing Media: WATER (FOAM), DRY CHEMICAL, CARBON DIOXIDE. Fire Fighting Procedures:IF POSSIBLE, STOP FLOW OF HEXANE. USE WATER SPRAY TO COOL SURROUNDING CONTAINERS.

Unusual Fire/Explosion Hazard:NONE.

Spill Release Procedures: EVACUATE ALL PERSONNEL

CERTAIN TO PURGE PIPING WITH AN INERT GAS PRIOR TO ATTEMPTING REPAIR. IF LEAK IS IN USER'S EQUIPMENT, BE CERTAIN TO PURGE PIPING WITH AN INERT GAS PRIOR TO ATTEMPTING REPAIR. IF LEAK IS IN C ONTAINER VALVE, CONTACT YOUR CLOSEST SUPPLIER.
Neutralizing Agent:NONE.
=========== Handling and Storage ===========
Handling and Storage Precautions:PROTECT CYLINDER FROM PHYSICAL DAMAGE. STORE IN COOL, DRY, WELL-VENTILATED AREA OF NONCOMBUSTIBLE CONTRSUCTION AWAY FROM HE AVILY TRAFFICKED AREAS. Other Precautions:DO NOT ALLOW THE TEMPERATURE WHERE CYLINDERS ARE STORED TO EXCEED 125F. CYLINDERS SHOULD BE STORED UPRIGHT AND FIRMLY SECURED TO PREVENT FALLING OR BEING KNOCKED OVER. FULL AND
EMPTY CONTAINERS SHOULD BE SEGREGATED.
====== Exposure Controls/Personal Protection =======
Respiratory Protection:POSITIVE PRESSURE AIR LINE WITH MASK OR SELF-CONTAINED BREATHING APPARATUS SHOULD BE AVAILABLE. Ventilation:HOOD WITH FORCED VENTILA TION, LOCAL EXHAUST TO PREVENT
ACCUMULATION ABOVE TWA. MECHANICAL IN ACCORDANCE WITH ELECTRIC. Protective Gloves:BUTYL RUBBER, PVC, POLYETHYLENE. Eye Protection:SAFETY GOGGLES OR GLASSES.  Other Protective Equipment:SAFETY SHOES, SAFETY SHOWER, EYEWASH FOUNTAIN.
Work Hygienic Practices:WASH AFTER HANDLING. Supplemental Safety and Health FLAMMABLE LIQUID.
========= Physical/Chemical Properties ==========
HCC:F2 Boiling Pt:B.P. Text:156F,69C Vapor Pres:2.5 Vapor Density :-140F Spec Gravity:3 Evaporation Rate & Description of the Computer of the
Solubility in Water:NEGLIGIBLE Appearance and Odor:CLEAR LIQUID WITH MILD ODOR.
========= Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES OXYGEN, OTHER OXIDIZERS. Stability Condition to Avoid:NONE. Hazardous Decomposition Products:NONE.
======= Disposal Considerations ==========
Waste Disposal Methods:DO NOT ATTEMPT TO DISPOSE OF WASTE OR UN

FROM AFFECTED AREA. USE

## **USED**

QUANTITIES. RETURN IN THE SHIPPING CONTAINER PROPERLY LABELED, WITH ANY VALVE OUTLET PLUGS OR CAPS SECURED AND VALVE PROTECTION CAP IN PLACE TO YOUR SUPPLIER.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any p erson utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.