View NSN Online: https://aerobasegroup.es/nsn/9150-00-068-6268

FISKE BROTHERS REFINING CO -- LUBRIPLATE 930 AAA -- 9150-00-068-6268

Product ID:LUBRIPLATE 930 AAA

MSDS Date:05/01/1987

FSC:9150

NIIN:00-068-6268

MSDS Number: BCXDW === Responsible Party ===

Company Name: FISKE BROTHERS REFINING CO

Address:129 LOCKWOOD ST

City:NEWARK

State:NJ

ZIP:07105-4720 Country:US

Info Phone Num:201-589-9150

Emergency Phone Num:201-589-9150

Pr

eparer's Name: ROBERT J. SIBILIA

CAGE:9N579

=== Contractor Identification ===

Company Name: FISKE BROS REFINING CO

Address:129 LOCKWOOD ST

Box:City:NEWARK

State:NJ

ZIP:07105-4720

Country:US

Phone:201-589-9150

CAGE:73219

Company Name: FISKE BROTHERS REFINING CO

Address:1500 OAKDALE AVE

Box:City:TOLEDO

State:OH ZIP:43605 Country:US

Phone:419-691-2491

CAGE:9N579

Company Name: INDUSTRIAL SUPPLY CORP

Address:1905 WESTWOOD AVE

Box:6356

City:RICHMOND

State:VA ZIP:23230 Country:US

Phone:804-355-8041

CAGE:6A

==========	Composition/	Information or	n Ingredients	==========
------------	--------------	----------------	---------------	------------

Ingred Name: MINERAL OIL, UNSPECIFIED

Other REC Limits: NONE SPECIFIED

OSHA PEL:100 PPM ACGIH TLV:100 PPM

Ingred Name: ADDITIVES

Other REC Limits: NONE SPECIFIED

Ingred Name:THICKENER

Other REC Limits: NONE SPECIFIED

========== Hazards Identification ===========================

LD50 LC50 Mixture:LD50 (ORAL RAT) IS NOT AVAILABLE Routes of Entry: Inhalation:NO Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:NO

IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ACUTE: EYE:MAY BE MILDLY IRRITATING.
SKIN:RELEASE DURING HIGH PRESSURE USAGE MAY RESULT IN INJECTION OF
OIL INTO THE SKIN CAUSING LOCAL NECROSIS. INGESTION- HIGH
TEMPERATURE VAPORS IRRITATE RESPIRATOR Y TRACT. INGESTION: MILD
STOMACH DISTRESS. CHRONIC: SKIN DISORDERS.

Explanation of Carcinogenicity: NONE OF THE COMPOUNDS IN THIS PRODUCT IS LISTED BY IARC, NTP, OR OSHA AS A CARCINOGEN.

Effects of Overexposure: EYES: REDNESS, TE

ARNG. SKIN: REDNESS, RASH.

INGESTION: NAUSEA, VOMITING.

Medical Cond Aggravated by Exposure:PRE-EXISTING SKIN DISORDERS MAY BE AGGRAVATED BY EXPOSURE TO THIS PRODUCT.

First Aid:INHALATION: REMOVE TO FRESH AIR. GIVE OXYGEN IF BREATHING IS DIFFICULT. GET MEDICAL ATTENTION. EYE: FLUSH WITH WATER FOR 15 MINUTES WHILE HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN: WASH WITH S OAP & WATER/WATERLESS CLEANER.

REMOVE CONTAMINATED

CLOTHING. IF IRRITATION PERSISTS, GET MEDICAL ATTENTION. INGESTION: DO NOT INDUCE VOMITING. IN GENERAL, NO TREATMENT IS REQUIRED. GET MEDICAL ADVICE.

============ Fire Fighting Measures =========================

Flash Point Method:COC

Flash Point:400F,204C

Lower Limits: 0.9 %

Upper Limits:7.0 %

Extinguishing Media: USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY CHEMICAL.

Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED

SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY.

Unusual Fire/Explosion Hazard: COMBUSTION OR HEAT OF FIRE MAY PRODUCE HAZARDOUS DECOMPOSITION PRODUCTS AND VAPORS.

======== Accidental Release Measures ===========

Spill Release Procedures:SCOOP UP EXCESS GREASE. CLEAN AREA WITH APPROPRIATE CLEANER.

Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.

Handling and

Storage Precautions:STORE IN A COOL, DRY PLACE WITH ADEQUATE VENTILATION. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE. KEEP AWAY FROM OPEN FLAMES & HIGH TEMPERATURES.

Other Precautions:MINIMIZE SKIN CONTACT. WASH WITH SOAP & WATER BEFORE EATING, DRINKING, SMOKING OR USING TOILET FACILITIES. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE. PROPERLY DISPOSE OF CONTAMINATED LEATHER ARTICLES (SHOES) THAT CAN NOT BE DECONTAMINATED.

	=====	Exposure	Controls/F	ersonai	Pro
tection =	======	=====			

Respiratory Protection:IF VENTILATION DOES NOT MAINTAIN INHALATION EXPOSURES BELOW PEL(TLV), USE NIOSH/MSHA APPROVED RESPIRATORS AS PER CURRENT 29 CFR 1910.134, INSTRUCTIONS/WARNINGS. RESPIRATORY PROTECTION NOT ORDINARILY R EQUIRED.

Ventilation: NONE REQUIRED

Protective Gloves: NEOPRENE RUBBER AS REQUIRED.

Eye Protection: SAFETY GLASSES RECOMMENDED.

Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER.

INDUSTRIAL-TYPE WORK CLOTHING AND APRON AS REQUI

RED.
Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR

Supplemental Safety and Health DO NOT GET IN EYES OR ON CLOTHING.

======== Physical/Chemical Properties ==========

HCC:V6
Boiling Pt:B.P. Text:>550F,>288C
Vapor Pres:5
Spec Gravity:0.97
Evaporation Rate & Description Reference:

FOOTWEAR.