

THE COSMIN CORP(MFR),CHEMICAL COMMODITIES(DIST). -- COPPERAS -- 6810-00-550-7452

===== Product Identification =====

Product ID:COPPERAS

MSDS Date:01/01/1985

FSC:6810

NIIN:00-550-7452

MSDS Number: BFDXC

=== Responsible Party ===

Company Name:THE COSMIN CORP(MFR),CHEMICAL COMMODITIES(DIST).

CAGE:OO299

=== Contractor Identification ===

Company Name:THE COSMIN CORP(MFR),CHEMICAL COMMODITIES(DIST).

CAG

E:OO299

===== Composition/Information on Ingredients =====

Ingred Name:FERROUS SULFATE (SARA III)

CAS:7782-63-0

RTECS #:NO8510000

Fraction by Wt: 98.0%

OSHA PEL:1 MG FE/M3

ACGIH TLV:1 MG FE/M3; 9192

EPA Rpt Qty:1000 LBS

DOT Rpt Qty:1000 LBS

===== Hazards Identification =====

Effects of Overexposure:ABDOMINAL

PAIN,RETCHING,DIARRHEA,DEHYDRATION,SHOCK,PALLOR,CYANOSIS,RAPID OR

WEAK PULSE,LOW BLOOD PRS

===== First Ai

d Measures =====

First Aid:SYMPTOMATIC THERAPY;ALSO METHYLROSANILINE CHLORIDE I.V.(FOR GRAY CYANOSIS),METHIONINE,VITAMINS E & B COMPLEX.

CAUTION:DIMERCAPROL CONTRAINDICATED IN IRON POISONING.INHAL:MOVE TO FRESH AIR.EYES:FLUSH W /H*2O FOR 15 MINS.SKIN:FLUSH

W/H*2O.INGESTIGIVE ML

===== Fire Fighting Measures =====

Extinguishing Media:ANY MEDIA

Fire Fighting Procedures:NONE

Unusual Fire/Explosion Hazard:NONE

=====

Accidental Release Measures =====

Spill Release Procedures:FLUSH WITH WATER,NEUTRALIZE WITH LIME.

===== Handling and Storage =====

Handling and Storage Precautions:FERROUS SULPHATE IS NOT DANGEROUS.HANDLE AS ANY NON-TOXIC INORGANIC SALT.KEEP IN COOL,DRY AREA.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:U.S.BUREAU OF MINES APPROVED.

Ventilation:MECHANICAL

Protective Gloves:RUBBER/HEOPREN

E

Eye Protection:CHEMICAL SAFETY GLASSES.

Other Protective Equipment:RUBBER APRONS.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

HCC:V1

Boiling Pt:B.P. Text:572F

Vapor Pres:UNK

Vapor Density:UNK

Spec Gravity:1.89

Solubility in Water:32.8G/100G

Appearance and Odor:BLUE-GREEN MONOCLINIC SOLID,ODOR SHARP.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

ALKALIES,SOLUBLE CARBONATE

S,GOLD & SILVER SALT,IODIDE,DECOCT

Stability Condition to Avoid:MOISTURE

Conditions to Avoid Polymerization:MOISTURE

===== Disposal Considerations =====

Waste Disposal Methods:FOLLOW STATE & LOCAL REGULATIONS & FEDERAL LAWS IF APPLICABLE.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly o

r implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.