

Product ID:TB1361D (C) MSDS Date:01/01/1987 FSC:8030 NIIN:00-823-7917 **MSDS Number: BFQYH** === Responsible Party === Company Name: THREE BOND OF AMERICAN, INC. Emergency Phone Num:213-879-9143 CAGE:60859 === Contractor Identification === Company Name: THREE BOND OF AMERICA, INC. Address:20815 HIGGINS COURT Box:City:TORRANCE State:CA ZIP:90501 Country:US Phone:310-320-33 42 CAGE:60859

Ingred Name:DIMETHACRYLATE ESTELS Fraction by Wt: 66.0%

Ingred Name:PLASTICIZER Fraction by Wt: 32.0%

Ingred Name:TERTIARY AMINE Fraction by Wt: 1.0%

Ingred Name:CATALYST Fraction by Wt: 1.0%

Effects of Overexposure: EYE/SKIN IRRITANT. POTENTIAL SKIN SENSITIZER.

First Aid

:SKIN:FLUSH W/WATER. EYES:FLUSH WITH WATER FOR 15 MIN.SEE DR. WASH SOILED CLOTHES BEFORE RE-USE.DISCARD CONTAMINATED SHOES.

Flash Point:> 200 F, 93 C CC Extinguishing Media:FOAM,CO*2 OR DRY CHEM,WATERSPRAY. Fire Fighting Procedures:COOL ALL CONTAINERS NOT IGNITED WITH FIRE HOSES.

Unusual Fire/Explosion Hazard:RAPID POLYMERIZATION MAY OCCUR AT HIGH TEMP.SMOKE MAY CONTAIN MONOMER IRRITATE LUNGS

Spill Release Procedures: AVOID EYE AND SKIN CONTACT, OR ORAL INGESTION. WEAR PROTECTIVE EQUIP. WASH AREA WELL AND COLLECT MATERIAL FOR INCINERATION

Handling and Storage Precautions:STORE IN A COOL PLACE OUT OF DIRECT SUNLIGHT.CHANGE OF CLOTHING SHOULD BE AVAILABLE.AT END OF SHIFT WORKER SHOULD SHOWER TO REMOVE VAPORS FROM PORES.
Other Precautions:FIRE FIGHTERS MOST
WEAR SELF-CONTAINED AIR SUPPLY. SHOES SHOULD BE AIRED OUT DAILY.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:NO SPECIAL VENTILATION REQUIRED. Ventilation:LOCAL EXHAUST,NORMAL VENTILATION ADEQUATE Protective Gloves:IMPERVIOUS Eye Protection:CHEM.SAFETY GOGGLES Other Protective Equipment:IMPERVIOUS OVERSHOES AND PROTECTIVE CLOTHING Supplemental Safety and Health

HCC:N1 Boili ng Pt:B.P. Text:>6000F Evaporation Rate & amp; Reference:< ETHER Appearance and Odor:BLUE LIQUID Percent Volatiles by Volume:0.5

Stability Indicator/Materials to Avoid:NO PEROXIDES,STRONG OXIDIZING AGENTS,IRON RUST STRONG BASES Stability Condition to Avoid:>90F,EXPOSURE TO LIGHT,OPEN FLAME,METAL CONTACT,VACUUM Hazardous Decomposition Products:CO AND CO*2

Waste Disposal Methods:CHEM.INCINERATOR.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of thi s information to their particular situation.