View NSN Online: https://aerobasegroup.es/nsn/6850-01-266-4555

MAGNAFLUX CORPORATION -- ZE-4B ZYGLO EMULSIFIER -- 6850-01-266-4555

========= Product Identification ==============

Product ID:ZE-4B ZYGLO EMULSIFIER

MSDS Date:01/29/1988

FSC:6850

NIIN:01-266-4555

MSDS Number: BGRZN === Responsible Party ===

Company Name: MAGNAFLUX CORPORATION

Address:7300 W. LAWRENCE AVENUE

City:CHICAGO

State:IL ZIP:60656 Country:US

Info Phone Num:312-867-8000

Emergency Phone Num:312-867-8000 Preparer's Name:BRUCE C. GRAHAM

CAGE:37676

=== Contractor Identification ===

Company Name: ILLINOIS TOOL WORKS INC MAGNAFLUX DIV

Address:3624 WEST LAKE AVENUE

Box:City:GLENVIEW

State:IL ZIP:60025 Country:US

Phone:847-657-5300/

CAGE:37676

====== Composition/Information on Ingredients ========

Ingred Name: DISTILLATES (PETROLEUM), HYDOTREATED HEAVY NAPHTHENIC

CAS:64742-52-5 RTECS #:PY8035000 Fraction by Wt: >60.0%

Ingred Name: TERPINEOL, ALPHA-

CAS:98-55-5

RTECS #:WZ6700000

Fraction by

Wt: 10.0%
======================================
Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Health Hazards Acute and Chronic:ACUTE:MAY IRRITATE EYES.SEE OVEREXPOSURE SYMPTOMS. Effects of Overexposure:INHALATION:NOT LISTED BY MANUFACTURER.HOWEVER,FINE SPRAY/MIST MAY CAUSE IRRITATION TO BREATHING PASSAGES; EYES:LIQUID/MIST CAUSES IRRITATION; SKIN:PROLONGED OR REPEATED CONTACT CAUSES IRRITATION BY DI SSOLVING SKIN OILS; INGESTION:NOT NO TEDBY MANUFACTURER. Medical Cond Aggravated by Exposure:NONE SPECIFIED BY THE MANUFACTURER
======================================
First Aid:INHALATION:REMOVE TO FRESH AIR; SKIN:REMOVE CONTAMINATED CLOTHES.WASH OFF PROMPTLY WITH SOAP AND WATER.USE SOOTHING LOTION.GET MEDICAL HELP IF IRRITATION PERSISTS; EYES:IMMEDIATELY RINSE EYES WITH COP IOUS AMOUNT OF WATER.GET MEDICAL ASSISTANCE IF IRRITATION PERSISTS; INGESTION:NOT STATED BY MANUFACTURER.GET
MEDICAL ATTENTION IF INGESTED.
======================================
Flash Point Method:PMCC Flash Point:>200F/>93C Lower Limits:6.0 Upper Limits:1.0 Extinguishing Media:CARBON DIOXIDE,FOAM Fire Fighting Procedures:KEEP CONTAINERS COOL WITH WATER SPRAY Unusual Fire/Explosion Hazard:WHEN INVOLVE IN COMBUSTION,MAY EMIT TOXIC GASES AT OR ABOVE DECOMPOSITION TEMPERATURE.
========= Accidental Release Measures ==========
Spill Release Procedu res:REMOVE IGNITION SOURCES.SM QTY:WIPE UP OR MOP BUT DO NOT BREATHE VAPORS.PLACE RAGS IN CLOSED DRUMS; LG QTY:WEAR PERSONAL SAFETY EQUIPMENTS.DIKE AREA FOR AHEAD.ABSORB LIQUID WITH COMMERCIAL ABSORBENT.T RANSFER WASTE MATL IN SALVAGE TANKS.

Handling and Storage Precautions:STORE AWAY FROM HEAT SOURCE IN WELL VENTILATED AREA.AVOID AGAINST PHYSICAL DAMAGE TO CONTAINERS.KEEP CONTAINERS TIGHTLY CLOSED.

Other P

recautions:DO NOT BREATHE VAPORS.DO NOT SMOKE WHILE USING.DO NOT HEAT ABOVE 130F(54C).AVOID FREQUENT OR PROLONGED SKIN CONTACT.
======= Exposure Controls/Personal Protection ========
Respiratory Protection:USE NIOSH APPROVED RESPIRATOR FOR CONFINED AREAS.
Ventilation:GENERAL ROOM VENTILATION TO KEEP BELOW TLV LIMITS. Protective Gloves:USE NITRILE RUBBER GLOVES IF NEEDED. Eye Protection:FULL GOGGLES/SAFETY GLASSES W/SIDESHIELD Other Protective Equipment:NOT KNOWN Work Hygie
nic Practices:WASH OFF PROMPTLY WITH WATER.AVOID SKIN CONTACT.
Supplemental Safety and Health NSN FOR KIT/SET OF MIL-I-25135D, TYPE II, METHOD B MATL; SET CONSISTS OF SKL-LO PENETRANT AND ZE-3 OR ZE-4B EMULSIFIER. THIS ENTRY FOR ZE-4B; QPL-25135-15 ALSO QUALIFIED ZE-3 & ZE-4B EMULSIFIERS FOR VARIOU S KITS TO GO WITH DIFFERENT PENETRANTS UNDER TYPE I, METHODS A,B,C,D & LEVELS 1,2,3,4; SEE OTHER PNI FOR OTHER PRODUCTS.
======================================
===
HCC:N1 Boiling Pt:B.P. Text:410F/210C Vapor Pres:0.25 @100F Vapor Density:>1.0 Spec Gravity:0.92 Solubility in Water:NEGLIGIBLE Appearance and Odor:PINK OILY LIQUID
======================================
Stability Indicator/Materials to Avoid:YES NOT KNOWN
Stability Condition to Avoid:HEAT,HIGH TEMPERATURES Hazardous Decomposition Products:EMITS OXIDES OF CARBON WHEN BURNING.
========= Disposal Considerations =============
Waste Disposal

Methods:INCINERATE OR DISPOSE OF AS EPA HAZARDOUS WASTE D001 (IGNITABLE WASTE),IN ACCORDANCE WITH ALL APPLICABLE FEDERAL,STATE,LOCAL REGULATIONS;IF LOCAL AUTHORITIES PROHIBIT DUMPING RINSINGS DOWN THE SEWER,P URFIY RINSINGS WITH MAGNAFLUX WASTEWATER.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied,

warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.