View NSN Online: https://aerobasegroup.es/nsn/8010-00-935-7069

PRATT & LAMBERT INC -- LACQUER, ACRYLIC O.D. 14084, ID 794416 -- 8010-00-935-7069

Product ID:LACQUER, ACRYLIC O.D. 14084, ID 794416

MSDS Date:09/12/1990

FSC:8010

NIIN:00-935-7069

MSDS Number: BJFQH === Responsible Party ===

Company Name: PRATT & LAMBERT INC

Box:2153 City:WICHITA State:KS

ZIP:67201 Country:US

Info Phone Num:316-733-1361 Emergency Phone Num:316-733-

1361

**CAGE:PRATT** 

=== Contractor Identification ===

Company Name: PRATT & LAMBERT

Address:250 PETTIT AVE

Box:2153

City:BELLMORE

State:NY ZIP:11710 Country:US

Phone:800-647-2253

**CAGE:PRATT** 

Company Name: PRATT AND LAMBERT INC

Address:Box:6027 City:CLEVELAND

State:OH

ZIP:44101-1027 Country:US

Phone:216-566-2902

CAGE:61196

====== Composition/Information on Ingredients ========

Ingred Name:LEAD CHROMATE (OSHA-CEIL .1000) (SARA 313 REPORTABLE)

CAS:7758-97-6

RTECS #:GB2975000

Fraction by Wt

: < 5%

Other REC Limits: NONE SPECIFIED

OSHA PEL:.0500 MG/CU.M. ACGIH TLV:.0500 MG/CU.M.

Ingred Name: CYCLOHEXANONE (SARA III)

CAS:108-94-1

RTECS #:GW1050000 Fraction by Wt: 25% Other REC Limits:LFL 1.1 OSHA PEL:S, 50 PPM

ACGIH TLV:S, 25 PPM; 9293

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name: METHYL ETHYL KETONE (2-BUTANONE) (MEK) (SARA III)

CAS:78-93-3

RTECS #:EL6475000 Fraction by Wt: 25%

Other REC Limits:LFL 2.0/UFL 10.0 OSHA PEL:200 PPM/300 STEL ACGIH TLV:200 PPM/300STEL 9192

EPA R

pt Qty:5000 LBS

DOT Rpt Qty:5000 LBS

Ingred Name: BUTYL BENZYL PHTHALATE (SARA III)

CAS:85-68-7

RTECS #:TH9990000 Fraction by Wt: < 5%

Other REC Limits: NONE SPECIFIED

EPA Rpt Qty:100 LBS DOT Rpt Qty:100 LBS

Ingred Name: ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000 Fraction by Wt: 5%

Other REC Limits:LFL 3.0/UFL 13.0 OSHA PEL:400 PPM/500 STEL ACGIH TLV:400 PPM/500STEL;9192

Ingred Name:TOLUENE (SARA III)

CAS:108-88-3

RTECS #:XS5250000 Fraction by Wt: 10%

Other REC Limits:LFL 1.7/

**UFL 7.1** 

OSHA PEL:200 PPM/150 STEL

ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name: VOC 5.38 LB/GAL LESS WATER & NEGLIGIBLY PHOTOCHEMICALLY REACTIVE MATERIALS 646 G/L LESS WATER

RTECS #:9999999VO

Other REC Limits: NONE SPECIFIED

Ingred Name: VOC 21.76 LB/GAL SOLIDS 2611 G/L SOLIDS

RTECS #:9999999VO

Other REC Limits: NONE SPECIFIED

========== Hazards Identification ===========================

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Reports o

Health Hazards Acute and Chronic:SWALLOWING MAY CAUSE GASTROINTESTINAL IRRITATION & CHEMICAL PNEUMONITIS. MAY SEVERELY IRRITATE NOSE, THROAT, EYES & SKIN. OTHER EFFECTS: DAMAGE TO BLOOD FORMING, KIDNEYS, URINE, REPRODUCTIVE SYSTEM, B RAIN, & NERVOUS SYSTEM. DELIBERATELY CONCENTRATING AND INHALING CONTENTS MAY BE HARMFUL OR FATAL.

Explanation of Carcinogenicity: CHROMATES MAY CAUSE LUNG CANCER.

Effects of Overexposure: HEADACHES, D

IZZINESS, NAUSEA, VOMITING,

CONFUSION, LOSS OF APPETITE, METALLIC TASTE IN MOUTH, ANXIETY, CONSTIPATION, WEAKNESS, INSOMNIA, MUSCLE & JOINT PAIN, FINE TREMORS, NUMBNESS, HYPERACTIVITY, COL IC, & SEVERE IRRITATION REACTION IF PRODUCT IS SWALLOWED, INHALED, ABSORBED THROUGH SKIN, OR GETS INTO EYES.

Medical Cond Aggravated by Exposure:REPORTS HAVE ASSOCIATED PROLONGED AND REPEATED OVEREXPOSURE TO SOLVENTS WITH PERMANENT BRAIN AND NERVOUS SYSTEM DAMAGE. PREXISTING KIDNEY

**CONDITIONS MAY BE** 

AGGRAVATED BY EXPOSURES TO LEAD.

First Aid:SWALLOWING: DO NOT INDUCE VOMITING. CALL POISON CONTROL CENTER IMMEDIATELY. INHALATION: REMOVE TO FRESH AIR IMMEDIATELY. IF BREATHING STOPPED, GIVE CPR & KEEP WARM. EYE: FLUSH WITH LARGE AMOUNTS OF WA TER FOR 15 MINUTES LIFTING UPPER/LOWER LIDS CONTINUOUSLY. SKIN: REMOVE CONTAMINATED CLOTHING AND WASH AFFECTED AREA WITH SOAP & WATER. GET MED

## ICAL ATTENTION IMMEDIATELY FOR ANY OF THESE CONDITIONS.

Flash Point:24F/-4C

Lower Limits:SEE INGRED Upper Limits:SEE INGRED

Extinguishing Media: USE CARBON DIOXIDE, DRY CHEMICAL OR ALCOHOL FOAM FOR FLAMMABLE LIQUID FIRES. POLYMER FOAM IS PREFERRED FOR LARGE FIRES.

Fire Fighting Procedures:WATER MAY BE INEFFECTIVE BUT MAY BE USED TO COOL EXPOSED CONTAINERS TO PREVENT PRESSURE BUILDUP & POSSIBLE AUTO-IGNITE

EXPLOSION. USE FOG NOZZLES WITH WATER.

Unusual Fire/Explosion Hazard:OVEREXPOSURE TO DECOMPOSITION PRODUCTS MAY CAUSE A HEALTH HAZARD. SYMPTOMS MAY NOT BE IMMEDIATELY APPARENT. OBTAIN MEDICAL ATTENTION.

======== Accidental Release Measures ==========

Spill Release Procedures:KEEP SPECTATORS AWAY. ELIMINATE ALL IGNITE SOURCES, CONTAIN SPILL WITH INERT MATERIAL, TRANSFER LIQUID TO COVERED METAL CONTAINERS FOR DISPOSAL. USE ONLY NON-SPARKING TOOLS. PREVENT

CONTAMINATION OF S EWERS, STREAMS, & GROUNDWATER.

=========== Handling and Storage ==============

Handling and Storage Precautions:DO NOT STORE ABOVE 95 DEGREES F.
STORE LARGE QUANTITIES IN COMPLIANCE WITH OSHA 29CFR1910.106.
Other Precautions:NEVER WASH OR REUSE EMPTY CONTAINERS FOR ANY PURPOSE.
CONTAINERS SHOULD BE GROUNDED & BONDED TO RECEIVING CONTAINER. DO
NOT WELD, BRAZE, CUT OR USE PRESSURE TO EMPTY CONTAINERS. DISPOSE
AS HAZARDOUS W ASTE, IGNITABLE
D001, EP TOXIC D008.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: IN WELL VENTILATED AREAS, RESPIRATORY PROTECTION MAY NOT BE REQUIRED. IN RESTRICTED AREAS USE A NIOSH APPROVED CHEM CARTRIDGE RESPIRATOR. FOR SPRAYING USE MECH PREFILTER. IN CONFINED AREAS USE A NIOSH /MSHA APPROVED AIR SUPPLIED RESPIRATOR.

Ventilation:DILUTE & LOCAL EXHAUST RECOMMENDED TO CONTROL CONCENTRATE OF HAZARDOUS INGREDIENTS.\*\*

Protective Gloves:WEAR SOLVENT

IMPERMEABLE GLOVES.

Eye Protection: WEAR SAFETY SPECTACLES.

Work Hygienic Practices:DO NOT TAKE INTERNALLY. PREVENT SKIN CONTACT. KEEP AWAY FROM CHILDREN. WASH HANDS AND FACE BEFORE EATING OR DRINKING.

Supplemental Safety and Health

\*\* REMOVE DECOMPOSITION PRODUCTS THAT ARE GENERATED WHEN WELDING, CUTTING, OR BRAZING OBJECTS COATED WITH THIS PRODUCT. THIS PRODUCT CONTAINS LEAD, WHICH IF PRESENT IN WASTE AT 5.0 MG/L OR MORE AFTER BEING EXTRACTED, IS CONSIDERED EP TOXIC& A HAZ

ARDOUS WASTE UNDER

RCRA REGULATIONS. HAZARDOUS WASTE NO. WOULD BE D008.

Boiling Pt:B.P. Text:175 TO 312F
Vapor Density:> THAN AIR

Spec Gravity:1.0

Evaporation Rate & Evaporation R

Percent Volatiles by Volume:75

======== Stability and Reactivity Data ==========

Stability Indicator/Materials to Avoid:YES STRONG ACIDS OR ALKALINE MATERIALS. Stability Condition to Avoid:AVOID EXCESSIVE H EAT AND SOURCES OF IGNITION.

Hazardous Decomposition Products:BURNING, HEAT BY WELDING/CUTTING, PRODUCES SMOKE, CARBON MONOXIDE, CARBON DIOXIDE, AND OXIDES OF CHROMIUM. AND LEAD.

Conditions to Avoid Polymerization: KEEP AWAY FROM HEAT SPARKS AND FLAME.

=======================================	Disposal Considerations	
		,

Waste Disposal Methods:DISPOSE OF IN I/A/W FEDERAL, STATE & LOCAL LAWS. INCINERATE ONLY IN EPA PERMITTED FACILITY. DO NOT INCINERATE CLOSED CONTAINERS. OB

SERVE PRECAUTIONS FOR DISP OF FLAMMABLE MATERIALS.

CONTAMINATED ABSOR BENT MAY BE DISPOSED IN A HAZARD WASTE LANDFILL.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent p

rofessional advice to verify and assume responsibility for the suitability of this information to their particular situation.