Product ID:BBL PREPARED MEDIA (PLATES)

MSDS Date:10/31/1990

FSC:6550

NIIN:01-234-5062

MSDS Number: BNQDT === Responsible Party ===

Company Name: BECTON DICKINSON MICROBIOLOGY SYSTEMS

Address:250 SCHILLING CIRCLE

Box:243

City:COCKEYSVILLE

State:MD ZIP:21030 Country:US

Info Phone Num:301-584-7169

Emergency Phone Num:301-666-0100

CAGE:06531

=

== Contractor Identification ===

Company Name: BECTON DICKINSON AND CO MICROBIOLOGY SYSTEMS DIV

Address:250 SCHILLING CIRCLE

Box:City:HUNT VALLEY

State:MD

ZIP:21030-1103

Country:US

Phone:410-771-0101

CAGE:05545

Company Name: BECTON DICKINSON AND CO, BECTON DICKINSON DIV.

Address:1 BECTON DR City:FRANKLIN LAKES

State:NJ

ZIP:07417-1884

Country:US

Phone:201-847-4000, 800-333-4831

CAGE:06531

Company Name: CURTIN MATHESON SCIENTIFIC, INC.


Address:22745 SAVI RANCH PKWY

Box:City:YORBA LINDA

State:CA ZIP:9

Country:US Phone:714-637-2200 CAGE:6X755
====== Composition/Information on Ingredients =======
Ingred Name:PREPARED PLATED MEDIA
========== Hazards Identification ===========
LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER. Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:THIS PRODUCT CONTAINS NO HAZARDOUS MATERIALS AS DEFINED BY THE OSHA HAZARD COMMU NICATIONS STANDARD. HOWEVER, INDIVIDUALS WITH KNOWN OR SUSPECTED ALLEERTIES SHOULD ADVISE PHYSICIAN OF INCIDENT THAT MAY HAVE RESULTED IN EXPOSURE TO ANTIBIOTIC TREATED MEDIA. Explanation of Carcinogenicity:MFR SAID "NOT APPLICIABLE" IN THIS FIELD. Effects of Overexposure:MFR SAID "NOT APPLICIABLE" IN THIS FIELD. Medical Cond Aggravated by Exposure:MFR SAID "NOT APPLICIABLE" IN THIS FIELD.
======================================
First Aid:MFR S AID "NOT APPLICIABLE" IN THIS FIELD.
============ Fire Fighting Measures =============
Flash Point:N/D Lower Limits:N/D Upper Limits:N/D Extinguishing Media:WATER SPRAY. Fire Fighting Procedures:MFR SAID "NOT APPLICIABLE" IN THIS FIELD. Unusual Fire/Explosion Hazard:PRODUCT WILL NOT BURN. IF PROD BECOMES INVOLVED IN A FIRE SITUATION EXTING MEDIA FOR SURROUNDING MATERIAL SHOULD BE APPROPRIATE.
======== Accidental Release Measures ==========
Spill

2687-7904



## **SHED**

PRECAUTIONS AGAINST MICROBIOLOGICAL HAZARDS THROUGHOUT ALL PROCEDURES. AFTER USE, PREPARED PLATES, SPECIMEN CONTAINERS AND OTHER CONTAMINATED MATERIALS MU ST BE STERILIZED BY AUTOCLAVING. (CONT OTHER PREC)

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and

disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.