View NSN Online: https://aerobasegroup.es/nsn/9140-00-286-5296

CENEX/LAND O LAKES AG SERVICES -- KEROSENE, DIESEL FUEL NO 1 D, NO 2 D -- 9140-00-286-5296

Product ID:KEROSENE, DIESEL FUEL NO 1 D, NO 2 D

MSDS Date:07/01/1987

FSC:9140

NIIN:00-286-5296

MSDS Number: BPFWL === Responsible Party ===

Company Name: CENEX/LAND O LAKES AG SERVICES

Box:1450

City:MINNEAPPOLIS

State:MN

ZIP:55485-9087

Country:US

Info Phone Num:612-451-5151

Em

ergency Phone Num:612-451-5151

CAGE:KO281

=== Contractor Identification ===

Company Name: CENEX/LAND O LAKES AG SERVICES

Address:NW 9087

Box:1450

City:MINNEAPOLIS

State:MN

ZIP:55485-9087 Country:US

Phone:612-451-5151

CAGE:KO281

Company Name: CENEX/LAND O'LAKES AG SERVICES

Box:64089 City:ST PAUL State:MN

ZIP:55164-0089

Country:US

Phone:612-451-5151

CAGE:0LMC0

======= Composition/Information on Ingredients ========

Ingred Name:COMPLEX MIXTURE OF PARAFFINIC,OLEFINIC,NAPHTHENIC & AR

OMATIC HYDROCARBON Fraction by Wt: >95%

Other REC Limits: NONE RECOMMENDED

OSHA PEL:5 MG/M3 OIL MISTS ACGIH TLV:5 MG/M3 OIL MISTS

Ingred Name:BENZENE (SARA III)

CAS:71-43-2

RTECS #:CY1400000 Fraction by Wt: 100% PPM

Other REC Limits: NONE RECOMMENDED

OSHA PEL:1PPM/5STEL;1910.1028

ACGIH TLV:10 PPM; A2; 9293

EPA Rpt Qty:10 LBS DOT Rpt Qty:10 LBS

Ingred Name:SULFUR

CAS:7704-34-9

RTECS #:WS4250000 Fraction by Wt: 410F Lower Limits:0.6% Upper Limits:8.0%

Extinguishing Media: USE WATER FOG, CARBON DIO

XIDE, FOAM, OR DRY

CHEMICAL. A FORCED STREAM OF WATER COULD SCATTER FLAMES OF FIRE.

Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY.

Unusual Fire/Explosion Hazard:MAY FORM WATER VAPOR, CARBON MONOXIDE AND CARBON DIOXIDE. WATER RUNOFF TO SEWER MAY CARRY COMBUSTIBLE FUELS & CREATE A FIRE/EXPLOSION. MORE FIRE HAZARD IF >85F.

======	=======	Accide	ental R	elease
Measures	========	=====	===	

Spill Release Procedures:REMOVE SOURCE OF HEAT,SPARKS,FLAME,FRICTION & ELECTRICITY,INCLUDING INTERNAL COMBUSTION ENGINE.USE EXPLOSION-PROOF EQUIPMENT TO CLEAN UP.DIKE SPILL.PREVENT LIQUID FROM ENTERING SEWERS,WATERWAYS/LOW AR EAS.SOAK UP WITH SAWDUST,SAND,OIL DRY.SHOVEL/SWEEP

========== Handling and Storage ============

Handling and Storage Precautions:STORAGE-STORE IN COOL, DRY WELL-VENTILATED AREA IN CLOSED CONTAINER AWA

Y FROM HEAT, IGNITION SOURCES & OXIDIZERS.

Other Precautions: COMBUSTIBLE LIQUID. USE WITH ADEQUATE VENTILATION.
AVOID CONTACT WITH EYES, SKIN AND CLOTHING. LAUNDER CONTAMINATED
CLOTHING BEFORE REUSE. GROUND AND BOUND CONTAINERS TO PREVENT
STATIC SPARKS. USE EXP LOSION-PROOF ELECTRICAL SERVICES.

====== Exposure Controls/Personal Protection ========

Respiratory Protection: IN SITUATION WHERE VAPOR CONCENTRATIONS MAY EXCEED THE RECOMMENDED EXPOSURE LIMITS, A NIOSH-

APPROVED ORGANIC

VAPOR CARTRIDGE RESPIRATOR SHOULD BE WORN. USE SELF-CONTAINED SUPPLIED-AIR RESPIRATOR FOR E MERGENCIES.

Ventilation:GENERAL DILUTION OR MECHANICAL VENTILATION/EXPLOSION-PROOF LOCAL EXHAUST TO KEEP VAPOR BELOW RECOMMENDED EXPOSURE LIMITS

Protective Gloves: NEOPRENE, NITRILE, OR POLYVINYL ALCOHOL

Eye Protection: USE CHEMICAL SAFETY GOGGLES & FACESHIELD

Other Protective Equipment:EYE WASH STATION.BARRIER CREAMS SPECIFIC FOR PETROLEUM-BASED MATERIALS MAY BE USED WHEN G

LOVES ARE IMPRACTICAL.

Work Hygienic Practices:DO NOT TAKE INTERNALLY. AVOID SKIN CONTACT. WASH SKIN AFTER USING PRODUCT. DO NOT EAT, DRINK OR SMOKE IN WORK AREA.

Supplemental Safety and Health

EMPTY CONTAINERS MAY CONTAIN RESIDUE AND CAN BE DANGEROUS. DO NOT PRESSURIZE, CUT, WELD, BRAZE, SOLDER, DRILL, GRIND OR EXPOSE TO HEAT, FLAME; THEY MAY EXPLODE. DO NOT USE PRESSURE TO EMPTY DRUM OR DR UM MAY RUPTURE WITH EXPLOSIVE FORCE.

==		Physical/Chemical	Propertie
s	===========		

HCC:F4

Boiling Pt:B.P. Text:330F,166C

Spec Gravity: 0.80 - 0.87

Solubility in Water: INSOLUBLE

Appearance and Odor:WATER WHITE TO YELLOW COLOR LIQUID WITH MILD PETROLEUM ODOR

======== Stability and Reactivity Data ===========

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS

Stability Condition to Avoid:HIGH HEAT, SPARKS, OPEN FLAMES AND OTHER SOURCES OF IGNITION

Hazardous Decomposition Products: CARBON MONOXIDE, CARBON DIOXIDE

===

======= Disposal Considerations ============

Waste Disposal Methods:WASTE MAY BE BURNED IN AN APPROVED INCINERATOR. TREATMENT, STORAGE, TRANSPORTATION AND DISPOSAL MUST BE IN ACCORDANCE WITH ALL APPLICABLE LOCAL, STATE AND FEDERAL LAWS AND REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, ex

pressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.