Product ID:UNLEADED GASOLINE MSDS Date:01/02/1992 FSC:9130 NIIN:01-272-0983 **MSDS Number: BPMLZ** === Responsible Party === Company Name: KERN OIL AND REFINING CO Address: RT 6, 7724 EAST PANAMA LANE Box:336 City:BAKERSFIELD State:CA ZIP:93307 Country:US Info Phone Num:805-845-0761/800-346-5922POISON CTR Emergency Phone Num:805-845-0761/800-424-9300(CHEMTREC) CAGE:1 **JX71** === Contractor Identification === Company Name: KERN OIL AND REFINING CO Address: RT 6, 7724 EAST PANAMA LANE Box:336 City:BAKERSFIELD State:CA ZIP:93307 Country:US Phone:805-845-0761/800-424-9300(CHEMTREC) CAGE:1JX71 Ingred Name: GASOLINE (INCLUDING INGREDIENTS 2, 3, 4 AND 5) CAS:8006-61-9 RTECS #:LX3300000 Fraction by Wt: 100% Other REC Limits:NONE RECOMMENDED

Ingr

OSHA PEL:300 PPM/500 STEL

ACGIH TLV:300 PPM/500STEL;9293

ed Name:BENZENE (SARA III) CAS:71-43-2 RTECS #:CY1400000 Fraction by Wt: 3% Other REC Limits:NONE RECOMMENDED OSHA PEL:1PPM/5STEL;1910.1028 ACGIH TLV:10 PPM; A2; 9293 EPA Rpt Qty:10 LBS DOT Rpt Qty:10 LBS

Ingred Name:TOLUENE (SARA III) CAS:108-88-3 RTECS #:XS5250000 Fraction by Wt: 10% Other REC Limits:NONE RECOMMENDED OSHA PEL:200 PPM/150 STEL ACGIH TLV:50 PPM; 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:XYLENES (O-,M-,P- ISOMERS) (SARA III) CAS:1330-20-7 RTECS #:ZE2100000 Fr action by Wt: 10% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM/150 STEL ACGIH TLV:100 PPM/150STEL;9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:ETHYL BENZENE (SARA III) CAS:100-41-4 RTECS #:DA0700000 Fraction by Wt: 2% Other REC Limits:NONE RECOMMENDED OSHA PEL:100 PPM/125 STEL ACGIH TLV:100 PPM/125STEL 9293 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO

Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:YES

Health Hazards Acute and Chronic:ACUTE-HIGH VAPOR CONCENTRATIONS MAY CAUSE CNS

DEPRESSION;I.E.HEADACHE,NAUSEA,DROWSINESS,DIZZINESS.ACCIDENTAL INGESTION MAY CAUSE SIMILAR SYMPTOMS.IT IS AN ASPIRATION HAZARD.MAY CAUSE EYE IRRITATION,RE DNESS,TEARING & BURNING.PROLONGED/REPEATED SKIN CONTACT CAN CAUSE IRRITATION,DEFATTING & DERMATITIS.CHRONIC-DERMATITIS.

- Explanation of Carcinogenicity:CONTAINS BENZENE.MAY CAUSE BLOOD DISEASES INCLUDING LEUKEMIA.VAPORS MAY CAUSE KIDNEY CANCER IN MALE RATS.
- Effects of Overexposure:HIGH VAPOR CONCENTRATIONS MAY CAUSE CNS DEPRESSION; I.E. HEADACHE, NAUSEA, DROWSINESS, DIZZINESS. ACCIDENTAL INGESTION MAY CAUSE SIMILAR SYMPTOMS. IT IS AN ASPIRATION HAZARD. MAY CAUSE EYE IRRITATION, REDNESS, TEARING & BURNING. PROLONGED/REPEATED SKIN CONTACT CAN CAUSE IRRITATION, DEFATTING & DERMATITIS.
- Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING SKIN DISORDERS OR IMPAIRED RESPIRATORY FUNCTION MAY BE MORE SUSCEPTIBLE TO THE EFFECTS OF THE SUBSTANCE.

First Aid:CALL A PHYSICIAN IN ALL CASES.EYES:IMMEDIATELY FLUSH WITH WATER FOR 15 MINUTES,HOLDING EYELIDS OPEN.SKIN:WASH WITH SOAP & WATER.INHALED:REMOVE TO FRESH AIR & PROVIDE CPR/OXYGEN IF NECESSARY.ORAL:DO NO T INDUCE VOMITING.CALL A PHYSICIAN IMMEDIATELY.IF CONSCIOUS,DRINK MILK OR WATER.

Flash Point Method:PMCC
Flash Point:-45F,-43C
Autoignition Temp:Autoignition Temp Text:536F
Lower Limits:1.2%
Upper Limits:7.6%
Extinguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, DRY CHEMICAL OR HALON. WATER MAY BE INEFFECTIVE.
Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT & A FULL FACED SELF CONTAINED BREATHING APPARATUS/SUPPLIED-AIR RESPIRATOR.COOL FIRE EXPOSED CONTAINERS WITH WATER SPRAY.
Unusual Fi

re/Explosion Hazard:SEVERE FIRE & EXPLOSION HAZARD INDOORS, OUTDOORS OR SEWERS. VAPORS MAY TRAVEL TO IGNITION SOURCE & FLASH BACK. CONTAINERS MAY EXPLODE IN FIRE.

Spill Release Procedures:WEAR PROTECTIVE EQUIPMENTS.ELIMINATE ALL SOURCES OF IGNITION.USE EXPLOSION-PROOF TOOLS.SHUT OFF FUEL SOURCE.DIKE SPILL.PREVENT LIQUID FROM ENTERING SEWERS/WATERWAYS.RECOVER FREE LIQUID.ADD SAND,EARTH OR OTHER ABSORBEN

T MATERIAL.TRANSFER TOCONTAINER.

Handling and Storage Precautions:STORAGE-STORE IN ACCORDANCE WITH NATIONAL FIRE PROTECTION ASSOCIATION REGULATIONS.KEEP CONTAINERS CLOSED.HANDLE IN WELL-VENTILATED AREA.

Other Precautions:"EMPTY" CONTAINERS RETAIN RESIDUE AND CAN BE DANGEROUS.DO NOT PRESSURIZE,CUT,WELD,BRAZE,SOLDER,DRILL,GRIND OR EXPOSE SUCH CONTAINERS TO HEAT,FLAME,SPARKS.THEY MAY EXPLODE AND CAUSE INJURY/D

EATH.AVOID REPEATED OR PROLONGED CONTACT WITH SKIN.

======= Exposure Controls/Personal Protection ==========

Respiratory Protection:NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS OR ORGANIC VAPOR RESPIRATOR OR SUPPLIED-AIR RESPIRATOR, IF NEEDED. Ventilation:LOCAL/MECHANICAL (GENERAL) VENTILATION - EXPLOSION PROOF,

WELL GROUNDED EQUIPMENTS

Protective Gloves:RUBBER

Eye Protection: CHEMICAL SPLASH GOGGLES & FACE SHIELD

Other Protective Equipment: IMPERVIOUS CLOTHING TO AV

OID SKIN AND EYE

CONTACT. EYE WASH STATION & SAFETY SHOWER.

Work Hygienic Practices: AVOID CONTACT WITH EYES, SKIN OR CLOTHING. WASH HANDS AFTER USING PRODUCT. AVOID BREATHING VAPORS OR MISTS. Supplemental Safety and Health

HCC:F1 Boiling Pt:B.P. Text:75.0F,23.9C Vapor Pres:414 - 724 Vapor Density:>1 Spec Gravity:0.74 - 0.79 Viscosity: