Product ID:CARBON DIOXIDE MSDS Date:02/02/1991 FSC:4210 NIIN:00-202-7858 **MSDS Number: BRRJM** === Responsible Party === Company Name: ADM CORN SWEETENERS Address:4666 FARIES PARKWAY **City:DECATUR** State:IL ZIP:62525 Country:US Info Phone Num:217-424-5608 Emergency Phone Num:217-424-5608 CAGE:84168 === Contractor Identification === Company Name: ARCHER DANIELS MIDLAND CO Addr ess:4666 E FARIES PKWY Box:1470 City:DECATUR State:IL ZIP:62526-5666 Country:US Phone:217-424-5200/7418 CAGE:84168 Company Name: GENERAL FIRE EXTINGUISHER CORP Address:1685 SHERMER RD Box:City:NORTHBROOK State:IL ZIP:60062-5315 Country:US Phone:(708) 847-272-7500; 847-272-7500 CAGE:99539

Ingred Name:CARBON DIOXIDE CAS:124-38-9 RTECS #:FF6400000 Fraction by Wt: 99.9% Other REC Limits:NONE RECOMMENDED OSHA PEL:5000 PPM ACGIH TL LD50 LC50 Mixture:PEL(TWA)=5000PPM Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:SKIN:CONTACT WITH THE LIQUID CAN CAUSE FROSTBITE AND BURNS.INHAL:3-5%-INCREASED RESPIRATION AND HEADACHE.8-15%-HEADACHE, NAUSEA, VOMITING ... UNCONSCIOUSNESS, COMA, DEATH. Explanation of Carcinogenicity: THERE ARE NO INGRED **IENTS ABOVE 0.1%** WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP, IARC OR OSHA. Effects of Overexposure:INHAL:HEADACHE,NAUSEA,VOMITING.SKIN:BURNS. Medical Cond Aggravated by Exposure: PERSONS WITH PRE-EXISTING RESPIRATORY AILMENTS MAY BE AT INCREASED RISK FROM EXPOSURE. First Aid:INHAL:QUICKLY MOVE TO AN UNCONTAMINATED AREA AND INHALE FRESH AIR.GIVE OXYGEN OR ARTIFICIAL RESPIRATION IF NEEDED.FURTHER

TREATMENT SHOULD BE SYMPTOMATIC AND SUPPORTIVE.EYES:FLUSH WITH TEMPID WATER OR NORMAL SALINE.GET MEDICAL ATTENTION.SKIN:FLUSH WITH LUKEWARM WATER;NOT HOT WATER.GET MEDICAL ATTENTION.INGEST:NOT EXPECT;GAS AT ROOM TEMPERATURE.

Flash Point:NONE Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE. Fire Fighting Procedures:USE A SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE EQUIPMENT. Unusual Fire/Explosion Haz ard:PRESSURIZED CONTAINERS MAY BURST FROM HEAT OF FIRE.

Spill Release Procedures:EVACUATE PERSONNEL.USE APPROPRIATE PROTECTIVE EQUIPMENT.VENTILATE AREA.AVOID CONTACT WITH LIQUID,SOLID OR VAPOR.SHUT OFF SUPPLY VALVE.DO NOT REENTER UNTIL TLV IS BELOW 5000PPM. Neutralizing Agent:NONE

Handling and Storage Precautions: DO NOT STORE NEAR HEAT OR FLA

ME.USE PROPER VENTILATION.USE A SELF-CONTIANED BREATHING APPARATUS WHERE TLV IS EXCEEDED.

Other Precautions:NONE

====== Exposure Controls/Personal Protection ==========

Respiratory Protection:POSITIVE PRESSURE AIR LINE WITH FULL FACEPIECE.ESCAPE SELF-CONTAINED BREATHING APPARATUS SHOULD BE AVAILABLE. Ventilation:SUFFICIENT TO PREVENT ACCUMULATION ABOVE THE TLV. Protective Gloves:INSULATED,COLD-RESISTANT Eye Protection:SAFETY GLASSES;GOGGLES. Other Protective Equipme nt:NONE Work Hygienic Practices:USE PRUDENT SANITARY AND HYGENIC PRACTICES. Supplemental Safety and Health NONE

HCC:G3 Boiling Pt:B.P. Text:-109F,-79C Melt/Freeze Pt:M.P/F.P Text:-109F,-79C Vapor Pres:291PSIG@0F Spec Gravity:1.65 Solubility in Water:SOLUBLE Appearance and Odor:GAS;COLORLESS;ODORLESS Percent Volatiles by Volume:100

Stability Indicator/Materi als to Avoid:YES MANUFACTURER STATES NONE. Stability Condition to Avoid:MANUFACTURER STATES NONE. Hazardous Decomposition Products:MANUFACTURER STATES NONE. Conditions to Avoid Polymerization:FORMS WEAK CARBONIC ACID WITH WATER.

Waste Disposal Methods: VENTILATE CONTAMINATED AREAS.SOLID CARBON DIOXIDE SHOULD BE PLACED OUTSIDE TO SUBLIMATE.

Disclaimer (provided with this information by the compiling agencies): This inform

ation is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.