Product ID: ADHESIVE, PART 1 MSDS Date:07/08/1993 FSC:8040 NIIN:00-138-7982 Kit Part:Y MSDS Number: BTVWH === Responsible Party === Company Name: DELTA PLASTICS CO Address:280 SOUTH MAIN STREET Box:489 City:PIXLEY State:CA ZIP:93256 Country:US Info Phone Num:209-757-2010 Emergency Phone Num:209-757-2010 Preparer's Name: ERIC SKIFF CAGE:DO191 === Contractor Identification === Company Name: DELTA DPC, INC Address:983 E. LEVIN AVE. Box:City:TULARE State:CA ZIP:93274 Country:US Phone:209-686-1644 CAGE:0ND20 Company Name: DELTA PLASTICS CO. Address:280 MAIN ST. PO BOX 489 Box:489 City:PIXLEY State:CA ZIP:93256 Phone:209-757-2010 CAGE:DO191 Company Name: TECHCON SYSTEMS INC Address:1059 E BEDMAR ST Box:City:CARSON State:CA ZIP:90746-3601 Country:US CAGE:22975

Ingred Name: BISPHENOL A EPOXY RESIN CAS:25

068-38-6 Fraction by Wt: 100% Other REC Limits:NONE RECOMMENDED

Ingred Name:VOC: 0 LGS/GAL; 0 GRAMS/LITER RTECS #:9999999VO Other REC Limits:NONE RECOMMENDED

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:IRRITATION, SENSITIZATION, DERMATITIS Effects of Overexposure:IRRITATION, SENSITIZATION, DERMATITIS Medical Cond Aggravated by Exposure:ALLERGY, ECZEMA, OR SKIN CONDITIONS.

First Aid:EYES: IMMEDIATELY FLUSH EYES WITH WATER FOR AT LEAST 15 MINUTES. CALL A PHYSICIAN. SKIN: PROMPTLY WASH WITH MILD SOAP AND WATER. INGESTION: IF CONSCIOUS, GIVE LARGE QUANTITIES OF WATER. GET MEDICAL AT TENTION. INHALATION: REMOVE TO FRESH AIR. GIVE OXYGEN IF BREATHING IS DIFFICULT. OTHER: PROMPTLY REMOVE WET CONTAMINATED NON-IMPERVIOUS CLOTHING. WASH BEFORE REUSE.

======= Fire Fighting Me

=====

Flash Point:490F,254C Extinguishing Media:CARBON DIOXIDE, FOAM, DRY CHEMICAL, WATER SPRAY Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS. Unusual Fire/Explosion Hazard:AVOID HEAT, OPEN FLAMES, AND ELECTRIC SPARKS.

Spill Release Procedures: SOAK UP IN ABSORBENT MATERIAL AND FLUSH THE AREA WITH PLENTY OF WATER.

Handling and Storage Precautions:CAUTION: THIS SYSTEM CONTAIN AN EPOXY RESIN WITH AN AMINE HARDENER. IN CASE OF CONTACT, WASH IMMEDIATELY WITH SOAP AND WATER.

Other Precautions:FOR EYES, FLUSH W/WATER 15 MINUTES & CONSULT PHYSICIAN. AVOID SKIN OR EYE CONTACT. AVOID INHALATION OF VAPOR. USE GOOD VENTILATION, PARTICULARLY IF HEATED OR SPRAYED. THESE MATERIALS MAY CAUSE SKIN SE NSITIZATION OR OTHER ALLERGIC RESPONSES.

======= Exposure Controls/Personal Protecti

on ==============

Respiratory Protection:AIR MASK IF IN CONFINED AREA. Ventilation:LOCAL EXHAUST VENTILATION RECOMMENDED. Protective Gloves:IMPERVIOUS RUBBER GLOVES Eye Protection:ONLY OSHA APPROVED EYE PROTECTION EQUIP Other Protective Equipment:SAFETY SHOWER AND EYE BATH. USE COVERALLS OR APRON, GLOVES, ETC TO PROTECT AGAINST SKIN & CLOTHING CONTAMINATION. Work Hygienic Practices:REMOVE AND WASH CONTAMINATED CLOTHING BEFORE

REUSE.

Supplemental Safety and Health

Boiling Pt:B.P. Text:>392F,>200C Vapor Pres:1 Vapor Density:>1 Spec Gravity:1.17 (WATER=1) Viscosity:12000-16000CP Evaporation Rate & amp; Reference:NIL Solubility in Water:NIL Appearance and Odor:AMBER LIQUID Percent Volatiles by Volume:NIL

Stability Indicator/Materials to Avoid:YES STRONG ACIDS, BASES, AND MERCAPTANS IN BULK. AVOID STRONG OXIDIZING AGENTS. Stability Cond

ition to Avoid:AVOID STRONG ACIDS, BASES, AND MERCAPTANS IN BULK. AVOID ELEVATED TEMPERATURES. Hazardous Decomposition Products:CARBON MONOXIDE, CARBON DIOXIDE, ALDEHYDES, AMMONIA

Waste Disposal Methods:INCINERATE IN FURNACE OR BURY IN LANDFILL IN ACCORDANCE WITH FEDERAL, STATE, OR LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by

elements of the Department

of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.