

PARKER HANNIFIN CORP -- PARKER O-LUBE -- 4470-01-068-8337

===== Product Identification =====

Product ID:PARKER O-LUBE

MSDS Date:05/02/1988

FSC:4470

NIIN:01-068-8337

MSDS Number: BWHBC

==== Responsible Party ===

Company Name:PARKER HANNIFIN CORP

Address:2360 PALUMBO DR

Box:11751

City:LEXINGTON

State:KY

ZIP:40512

Country:US

Info Phone Num:606-269-2351

Emergency Phone Num:606-269-2351

CAGE:36460

==== C

ontractor Identification ===

Company Name:PARKER HANNIFIN CORP

Address:2360 PALUMBO DR

Box:City:LEXINGTON

State:KY

ZIP:40512

Country:US

Phone:606-269-2351

CAGE:36460

===== Composition/Information on Ingredients =====

Ingred Name:PETROLEUM NAPHTHA; (PETROLEUM NAPHTHENIC OIL)

Fraction by Wt: 70-75%

OSHA PEL:N/K

ACGIH TLV:N/K

Ingred Name:BARIUM SOAP

CAS:68201-19-4

Fraction by Wt: 25-30%

OSHA PEL:N/K

ACGIH TLV:N/K

===== Hazards Identification =====

=====

LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER.
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:EYES:MODERATE IRRITATION, REDNESS,
TEARING. SKIN:SLIGHT IRRITATION. SWALLOWING:GASTROINTESTINAL
IRRITATION, NAUSEA, VOMITING AND DIARRHEA. INHAL:NONE KNOWN.
Explanation of Carcinogenicity:NOT RELEVANT.
Effects of Overexposure:SEE HEALTH HAZARDS.
Medical Cond Aggravated by Exposure:NONE SP
ECIFIED BY MANUFACTURER.

===== First Aid Measures =====

First Aid:INHAL:REMOVE TO FRESH AIR. SUPPORT BREATHING (GIVE O₂/ARTF
RESP) . INGEST:IMMED DRINK 2 GLASSES OF WATER, INDUCE VOMIT. SEEK
MED ATTN. EYES:FLUSH W/LG AMTS OF WATER FOR @ LEAST 15 MINS,
LIFTING EYE LIDS OCCASNLY. SEEK MED ATTN. SKIN:WASH EXPOSED AREA
W/SOAP & WATER.

===== Fire Fighting Measures =====

Flash Point Method:OC

Flash Point:435F

,224C

Extinguishing Media:CARBON DIOXIDE, FOAM, AND DRY CHEMICAL.

Fire Fighting Procedures:NIOSH/MSHA APPRVD SCBA & FULL PROT EQUIP .

WATER/FOAM MAY CAUSE FROTHING, WHICH CAN BE VIOLENT, ESPECIALLY IF
SPRAYED INTO CNTNRS OF HOT BURNING LIQUID.

Unusual Fire/Explosion Hazard:NEVER USE WELDING/CUTTING TORCH ON OR
NEAR (EVEN EMPTY) BECAUSE PROD (EVEN JUST RESIDUE) MAY IGNITE AND
CAUSE AN EXPLOSION.

===== Accidental Release Measures =====

Spill Release Pr

ocedures:COLLECT IN BEAKER. LG SPILL-PERSONS NOT
WEARING PROT EQUIP SHOULD BE EXCLUDED FROM AREA OF SPILL UNTIL
CLEANUP HAS BEEN COMPLETED. SHOVEL MATL INTO CNTNR. REMAINING MATL
TAKEN UP W/ABSORBENT MATERIAL.

Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

===== Handling and Storage =====

Handling and Storage Precautions:NORMAL PRECAUTION - AVOID FIRE
HAZARDS.

Other Precautions:NONE.

===== Exposure Controls/Personal Protection =

=====

Respiratory Protection:NONE REQUIRED UNDER NORMAL USE. NIOSH/MSHA APPROVED RESPIRATOR APPROPRIATE FOR EXPOSURE OF CONCERN .

Ventilation:MECHANICAL (GENERAL).

Protective Gloves:NITRILE/NEOPRENE RUBBER GLOVES.

Eye Protection:ANSI APPROVED CHEM SAFETY GOGGLES

Supplemental Safety and Health

NONE SPECIFIED BY MANUFACTURER.

===== Physical/Chemical Properties =====

Boiling Pt:B.P. Text:700F,371C

Spec Gravity: