

DEXTER ADHESIVES & STRUCTURAL MATERIALS -- AS9280016;HYSOL EA 9396 PT.A QT SYSTEM;Z004AB(SHIP CODE) -- 8040-00-209-1286

===== Product Identification =====

Product ID:AS9280016;HYSOL EA 9396 PT.A QT SYSTEM;Z004AB(SHIP CODE)

MSDS Date:02/01/1994

FSC:8040

NIIN:00-209-1286

Kit Part:Y

MSDS Number: BYDJD

=== Responsible Party ===

Company Name:DEXTER ADHESIVES & STRUCTURAL MATERIALS

Address:2850 WILLOW PASS RD

Box:312

City:PITTSBURG

State:CA

ZIP:94565-3299

Country:US

Info Phone Num:202-483-7616

Emergency Phone Num:202-483-7616 800-424-9300(CHEMTREC)

Preparer's Name:MSDS DEPT (510-458-8000)

CAGE:33564

=== Contractor Identification ===

Company Name:DEXTER CORPORATION ADHESIVE & COATING SYSTEMS

Address:2850 WILLOW PASS ROAD

Box:312

City:BAY POINT

State:CA

ZIP:94565-3299

Country:US

Phone:202-483-7616

CAGE:33564

===== Composition/Information on Ingredients =====

Ingred Name:EPOXY RESIN,POLYFUNCTIONAL

Fraction by Wt: 30-60%

Other REC Limits:NO

NE RECOMMENDED

Ingred Name:BISPHENOL A & EPICHLOROHYDRIN RESIN

Fraction by Wt: 30-60%

Other REC Limits:NONE RECOMMENDED

Ingred Name:AMINE,ALIPHATIC

Fraction by Wt: 5-10%

Other REC Limits:NONE RECOMMENDED

===== Hazards Identification =====

LD50 LC50 Mixture:ORAL LD50 (RAT) IS >4000MG/KG INGRED #1

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:SKIN:MAY CAUSE IRRITATI

ON OR

SENSITIZATION.EYES/INHAL/INGEST:NOT REPORTED.

Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.1% WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP,IARC OR OSHA.

Effects of Overexposure:SKIN:IRRITATION,RASH.

Medical Cond Aggravated by Exposure:PERSONS WITH PRE-EXISTING SKIN AILMENTS MAY BE AT INCREASED RISK FROM EXPOSURE.

===== First Aid Measures =====

First Aid:SKIN:REMOVE CONTAMINATED CLOTHING;WASH WITH SOAP AND WATER.GET MEDICAL ATTENTION IF IRRITATION PERSISTS.EYES:FLUSH WITH WATER FOR 15 MINUTES.GET MEDICAL ATTENTION.INHAL:REMOVE TO FRESH AIR.GIVE OXYGEN OR ARTIFICIAL RESPIRATION IF NEEDED.GET MEDICAL ATTENTION IF SYMPTOMS PERSIST.INGEST:DO NOT INDUCE VOMITING.GET PROMPT QUALIFIED MEDICAL ATTENTION.IF CONSCIOUS,GIVE PLENTY OF WATER.

===== Fire Fighting Measures =====

Flash Point:NONE

Extinguishing Media:WATER FOG OR SPRAY,CARBON DIOXIDE,FOAM,DRY CHEMICAL,HALON.

Fire Fighting Procedures:USE A SELF-CONTAINED BREATHING APPARATUS AND FULL PROTECTIVE EQUIPMENT.

Unusual Fire/Explosion Hazard:FIRE CONDITIONS MAY EVOLVE TOXIC FUMES.

===== Accidental Release Measures =====

Spill Release Procedures:USE PROPER RESPIRATORY AND PROTECTIVE EQUIPMENT.VENTILATE AREA.SCRAPED UP OR SHOVEL INTO A PROPER CONTAINER FOR DISPOSAL.

Neutralizing Agent:NOT APPLICABLE.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN A COOL,DRY,WELL-VENTILATED PLACE.KEEP CONTAINER CLOSED WHEN NOT IN USE.KEEP AWAY FROM HEAT,SPARKS,FLAMES AND INCOMPATIBLE MATERIALS.

Other Precautions:PRODUCT MAY BE STORED AT ROOM TEMPERATURE FOR UP TO 12 MONTHS.ROTATE STOCK.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NOT NEEDED IN NORMAL SERVICE.

Ventilation:USE LOCAL EXHAUST AT POINT OF USE.

Protective Gloves:BUTYL OR NITRILE RUBBER

R,PVC.

Eye Protection:SAFETY GLASSES OR GOGGLES.

Other Protective Equipment:PROVIDE A LOCAL EYE WASH STATION AND SAFETY SHOWER.

Work Hygienic Practices:USE REASONABLE CARE IN HANDLING THIS PRODUCT.WASH HANDS AFTER USE AND BEFORE EATING.

Supplemental Safety and Health

KEY1;T6.

===== Physical/Chemical Properties =====

HCC:B2

Vapor Pres:NIL

Vapor Density:>1

Spec Gravity:1.16

Viscosity:400-1400P

Solubility in Water:NEGLIGIBLE

Appearance and Odor:PASTE;BLUE;SLIGH

T ODOR.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

STRONG OXIDIZING AGENTS,STRONG LEWIS ACIS OR MINERAL ACIDS.

Stability Condition to Avoid:AVOID MIXING MORE THAN 1 LB BATCHES OF PARTS A AND B.DO NOT HEAT THE MIXTURE ABOVE 125F.

Hazardous Decomposition Products:CARBON DIOXIDE,CARBON MONOXIDE,OXIDES OF NITROGEN,ALDEHYDES,ACIDS,UNDETERMINED ORGANICS.

Conditions to Avoid Polymerization:HEAT ABOVE 125F.

=====

== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document s

ould seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.