

AUFHAUSER BROTHERS CORP -- ALLOY 605,5796 -- 3439-00-204-3203

===== Product Identification =====

Product ID:ALLOY 605,5796

MSDS Date:05/01/1997

FSC:3439

NIIN:00-204-3203

MSDS Number: CFKQN

=== Responsible Party ===

Company Name:AUFHAUSER BROTHERS CORP

Address:39 WEST MALL

City:PLAINVIEW

State:NY

ZIP:11803-4209

Country:US

Info Phone Num:516-694-8696

Emergency Phone Num:516-694-8696/800-645-9486

CAGE:59401

=== Contractor Identification ===

Company Name:AUFHAUSER
CORP

Address:39 WEST MALL

Box:City:PLAINVIEW

State:NY

ZIP:11803-4209

Country:US

Phone:212-757-6824/FAX: 516-694-8690

CAGE:59401

===== Composition/Information on Ingredients =====

Ingred Name:MANGANESE (SARA 313)

CAS:7439-96-5

RTECS #:OO9275000

Fraction by Wt: 1 - 2%

Other REC Limits:NONE RECOMMENDED

OSHA PEL:C, 5 MG/M3 (FUME)

ACGIH TLV:0.2 MG/M3; 9596

Ingred Name:SILICON

CAS:7440-21-3

RTECS #:VW0400000

Fraction by Wt: 1% MAX

Other REC Limits:NONE RECOMMENDED

OSHA PEL:15 MG/

M3 TDUST
ACGIH TLV:10 MG/M3 TDUST; 9596

Ingred Name:CHROMIUM (SARA 313) (CERCLA)
CAS:7440-47-3
RTECS #:GB4200000
Fraction by Wt: 19 - 21%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:1 MG/M3
ACGIH TLV:0.5 MG/M3; 9596
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

Ingred Name:NICKEL (SARA 313) (CERCLA)
CAS:7440-02-0
RTECS #:QR5950000
Fraction by Wt: 9 - 11%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:1 MG/M3
ACGIH TLV:1 MG/M3; 9596

Ingred Name:TUNGSTEN,AS W,SOLUBLE COMPOUNDS.
CAS:7440-33-7
RTECS #:YO7175000
F
raction by Wt: 14 - 16%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:NOE ESTABLISHED
ACGIH TLV:1 MG/M3/3 STEL; 9596

Ingred Name:IRON
CAS:7439-89-6
RTECS #:NO4565500
Fraction by Wt: 3% MAX
Other REC Limits:NONE RECOMMENDED
OSHA PEL:10 MG/M3 (TDUST)
ACGIH TLV:5 MG/M3 (OXIDE FUME)

Ingred Name:COBALT (SARA 313)
CAS:7440-48-4
RTECS #:GF8750000
Fraction by Wt: BALANCE
Other REC Limits:NONE RECOMMENDED
OSHA PEL:0.1 MG/M3
ACGIH TLV:0.02 MG/M3; A3; 9596

===== Hazards Identification ===

=====

LD50 LC50 Mixture:LD50 (ORAL RAT) IS NOT RELEVANT.
Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO
Health Hazards Acute and Chronic:TARGET ORGANS:EYES, SKIN, CNS,
RESPIRATORY TRACT. ACUTE- INHALING FUMES CAN CAUSE IRRITATION,
DIZZINESS, Watery eyes, HEADACHE, NAUSEA, COUGHING, CHEST PAINS.
ARC RAYS CAN INJURE EYES & BURN SKIN. ELE CTRIC SHOCK CAN KILL. IR
RADIATION CAN INJURE EYES. INGESTION IS UN
LIKELY. CHRONIC- MAY
CAUSE LUNG DAMAGE, SIDEROSIS.
Explanation of Carcinogenicity:CONTAINS CHROMIUM.
Effects of Overexposure:IRRITATION, SKIN DERMATITIS OR ECZEMA, COUGH,
WHEEZING AND SHORTNESS OF BREATH, DECREASED PULMONARY FUNCTION,
HEADACHE, NAUSEA, VOMITING, WEAKNESS, CONVULSIONS, RESPIRATORY AND
SKIN SENSITIZATION, BUR NS, FEVER
Medical Cond Aggravated by Exposure:INDIVIDUALS WITH PRE-EXISTING
DISEASES OF THE EYE, SKIN, RESPIRATORY TRACT MAY HAVE INCREASED
SUSCEPTIBI
LITY TO THE TOXICITY OF EXCESSIVE EXPOSURES.

===== First Aid Measures =====

First Aid:GET MEDICAL ATTENTION IF SYMPTOMS PERSIST. EMPLOY FIRST AID
TECHNIQUE RECOMMENDED BY RED CROSS. IF BREATHING IS DIFFICULT,
PROVIDE OXYGEN/CPR. FOR ELECTRIC SHOCK, DISCONNECT POWER. FOR ARC
BURNS, APPL Y COLD, CLEAN COMPRESSES & CALL A PHYSICIAN. IF EYE
CONTACT, FLUSH WITH WATER FOR 15 MINUTES. IF SKIN CONTACT, WASH
WITH SOAP & WATER. INGESTION UNLIKELY
(WIRE).

===== Fire Fighting Measures =====

Flash Point:NONE
Lower Limits:NOT RELEVANT
Upper Limits:NOT RELEVANT
Extinguishing Media:TO EXTINGUISH METAL FIRE, USE DRY SAND, DRY
GRAPHITE OR OTHER CLASS "D" FIRE EXTINGUISHING POWDER.
Fire Fighting Procedures:TREAT AS A METALLIC FIRE. WEAR PROTECTIVE
CLOTHING AND NIOSH-APPROVED SELF-CONTAINED BREATHING APPARATUS.
Unusual Fire/Explosion Hazard:NONE

===== Accidental Release Measures =====

=====

Spill Release Procedures:NOT RELEVANT
Neutralizing Agent:NOT RELEVANT

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN DRY PLACE AWAY FROM ACIDS.
KEEP OUT OF REACH OF CHILDREN.
Other Precautions:AVOID EYE OR SKIN CONTACT. AVOID BREATHING FUMES. USE
WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING AND
BEFORE EATING AND DRINKING. REMOVE CONTAMINATED CLOTHING. LAUNDER
BEFORE REUSE.

===== Ex
posure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED SUPPLIED AIR RESPIRATORY
PROTECTION OR RESPIRABLE FUME RESPIRATOR WHEN WELDING, BRAZING OR
SOLDERING IN CONFINED SPACE OR WHERE LOCAL EXHAUST VENTILATION DOES
NOT KEEP EXPOSURE BELOW TLV.
Ventilation:LOCAL EXHAUST VENTILATION SHOULD BE USED TO CONTROL
EXPOSURE TO AIRBORNE FUMES OR DUST WHENEVER POSSIBLE.
Protective Gloves:WELDER'S (HEAT RESISTANT) WHEN WELDING
Eye Protection:WELDER'S GOGGLES WHEN WELDING
Other Protective Equipment:EYE WASH STATION, SAFETY SHOWER, APRON
(ALUMINIZED), EAR PROTECTION (TO AVOID EXCESSIVE NOISE)
Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND
RECOMMENDED PROCEDURES.
Supplemental Safety and Health

===== Physical/Chemical Properties =====

HCC:N1
NRC/State Lic Num:NOT RELEVANT
Viscosity:NOT RELEVANT
Evaporation Rate & Reference:NOT RELEVANT
Solubility in Water:INSOLUBLE
Appearance and Odor:

WELDING ROD

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid: YES

STRONG ACIDS

Stability Condition to Avoid: NONE

Hazardous Decomposition Products: WELDING FUMES (OXIDES OF METAL BEING WELDED) & GASES SUCH AS OZONE, CARBON MONOXIDE, CARBON DIOXIDE

===== Disposal Considerations =====

Waste Disposal Methods: PREVENT WASTE FROM CONTAMINATING SURROUNDING ENVIRONMENT. KEEP PERSONNEL AWAY. DISCARD ANY PRODUCT, RESIDUE, DISPOSABLE CONTAINER OR LINER IN AN ENVIRONMENTALLY ACCEPTABLE MANNER, IN FULL COMPLIANCE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.