

HEWLETT-PACKARD CO BOISE DIV -- HP LASER JET CARTRIDGE C3906A -- 6850-01-428-3583

===== Product Identification =====

Product ID:HP LASER JET CARTRIDGE C3906A

MSDS Date:01/16/1996

FSC:6850

NIIN:01-428-3583

Status Code:A

MSDS Number: CJCWV

=== Responsible Party ===

Company Name:HEWLETT-PACKARD CO BOISE DIV

Address:11311 CHINDEN BLVD

City:BOISE

State:ID

ZIP:83714

Country:US

Info Phone Num:208-396-6

000/323-2551

Emergency Phone Num:208-396-6000/323-2551

CAGE:18660

=== Contractor Identification ===

Company Name:HEWLETT-PACKARD CO BOISE DIV

Address:11311 CHINDEN BLVD

Box:City:BOISE

State:ID

ZIP:83714

Country:US

Phone:208-396-6000

CAGE:18660

Company Name:ODYSSEY GROUP THE

Address:245 LOCHAN CV STE B18

Box:000

City:ALPHARETTA

State:GA

ZIP:30202-7614

Country:US

Phone:800-250-8716/FAX 770-754-1194

Contract Num:SP0450-98-M-CJ31

CAGE:05NL2

===== Composition/Information on Ingredients ==

=====

Ingred Name:STYRENE ACRYLATE COPOLYMER,
CAS:25153-46-2
Minumum % Wt:45.
Maxumum % Wt:55.

Ingred Name:IRON OXIDE
CAS:1317-61-9
Minumum % Wt:45.
Maxumum % Wt:55.
OSHA PEL:10 MG/M3
ACGIH TLV:5 MG/M3

===== Hazards Identification =====

LD50 LC50 Mixture:LD50 (ORAL RAT) IS >5000 MG/M3
Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:MAY CAUSE EYE IRRITATION. UNLI
KELY TO
CAUSE SKIN IRRITATION. MINIMAL RESPIRATORY TRACT IRRITATION MAY
OCCUR AS WITH EXPOSURE TO LARGE AMOUNTS OF ANY TOXIC DUST.
INGESTION IS NOT APPLICABLE ROUTE OF EN TRY FOR INTENDED USE.
Explanation of Carcinogenicity:MANUFACTURER GAVE NO INFORMATION ABOUT
CARCINOGENICITY. HMIS DOES NOT EXPECT IT TO BE CARCINOGENIC.
Effects of Overexposure:EYES-IRRITATION. INHALED-MINIMAL RESPIRATORY
IRRITATION.
Medical Cond Aggravated by Exposure:MFR GAVE NO INFORMATION ON MSDS.

=====

===== First Aid Measures =====

First Aid:INGESTED-DILUTE STOMACH CONTENTS WITH SEVERAL GLASSES OF
WATER. IF SYMPTOMS OCCUR, CONSULT A PHYSICIAN. INHALED-REMOVE
VICTIM TO FRESH AIR. IF SYMPTOMS OCCUR, CONSULT A PHYSICIAN.
EYES-FLUSH WITH RUNN ING WATER FOR AT LEAST 15 MINUTES, IF SYMPTOMS
OCCUR, CONSULT A PHYSICIAN. SKIN-WASH WITH SOAP & WATER. IF
SYMPTOMS OCCUR, CONSULT A PHYSICIAN.

===== Fire Fighting Measures =====

=====

Extinguishing Media:WATER, DRY CHEMICAL, CO2
Fire Fighting Procedures:NONE.
Unusual Fire/Explosion Hazard:TONER MATERIAL LIKE MOST ORGANIC MATERIAL
IN POWDER FORM, IS CAPABLE OF CREATING A DUST EXPLOSION.

===== Accidental Release Measures =====

Spill Release Procedures:WEAR PERSONAL PROTECTIVE EQUIPMENT AS
DESCRIBED. MINIMIZE THE RELEASE OF PARTICULATES. VACUUM OR SWEEP
THE MATERIAL INTO A BAG OR OTHER SEALED CONTAINER AND DISPOSE OF IN
AC
CORDANCE WITH LOCAL REQUIRE MENTS. DO NOT DISCHARGE INTO DRAINS.
Neutralizing Agent:MFR GAVE NO INFORMATION ON MSDS.

===== Handling and Storage =====

Handling and Storage Precautions:KEEP OUT OF REACH OF CHILDREN. KEEP
FROM CONTACT WITH OXIDIZING MATERIALS. KEEP CONTAINER CLOSED AND
STORE AT ROOM TEMPERATURE. AVOID INHALATION OF DUST AND CONTACT
WITH EYES. KEEP AWAY FROM EXCESSIVE HEAT, SPARKS, AND OPEN FLAMES.
Other Precautions:NONE SPECIFIED BY
MANUFACTURER.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE REQUIRED UNDER INTENDED USE.
Ventilation:GOOD GENERAL VENTILATION SHOULD BE SUFFICIENT UNDER
INTENDED USE.
Protective Gloves:NONE REQUIRED UNDER INTENDED USE.
Eye Protection:NONE REQUIRED UNDER INTENDED USE.
Other Protective Equipment:NONE REQUIRED UNDER INTENDED USE.
Work Hygienic Practices:DLA-HMIS FOCAL POINT: USE GOOD INDUSTRIAL
HYGIENE PRACTICE. AVOID UNNECESSARY CONTACT.
WASH THOROUGHLY AFTER
HANDLING.
Supplemental Safety and Health

===== Physical/Chemical Properties =====

HCC:N1
NRC/State Lic Num:NONE
Melt/Freeze Pt: